

PRIMARY CORNER DESCRIPTION Sec. Cor. for Secs. 3 & 4 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 16 Page(s) 6691C -6691D)

6691D
Set a basalt stone, 18x10x8" 12" in the ground for cor. of secs. 3, 4, 9 and 10, marked with 5 notches on S and 3 notches on E edge, from which:
A R.Fir, 34" dia., bears N.41°E. 65 lks mkd T30S R1W S3 BT
A R.Fir, 18" dia. bears S.18°E. 33 lks mkd T30S R1W S10 BT
A R.Fir, 12" dia., bears S.55°W. 64 lks mkd T30S R1W S9 BT
A R.Fir, 16" dia. bears N.24°W. 57 lks mkd T30S R1W S4 BT.

6691C
(Sets CC for 9 & 10 & "I destroy marks on former corner and BTs referring to these sections.")

Reported as not fd. by JMP, DCSO 8/15/1969, C.S. 54/59-128: Chained W 250 lks. 165.0 ft. (from CC S9 & 10) Fd. 1 tree old axe work very small face. Tree cut down to rotten for good ring count but approx. old enough., good bearing & dist. form approx. cor. to this tree but no def. evidence.

Dennis Gaylord, USFS & Deputy Co. Surveyor - Witness: Rolland Simshauser - Oct. 20, 1977 - C.S. File 59/40-51

Found - A 14" now 18" D.Fir stump bears N.41°E., 42.9 ft. stump is nearly covered by dirt. After considerable digging, I open a small portion of the healed blaze and find scribing & reverse scribing.
The BTs to the NW, SW and the SE are all gone. (extensive logging in the vicinity).
Set - 1½" Galv IP with 2½" brass cap stamped County Surveyors Office T 30 S R 1 W 1977
S 4 | S 3
ONLY

I place a stone mound around the pipe 2'x2'x1' high. Set by reference to only remaining orig. bearing tree.
New BTs- A 6" G.Fir bears N.64°E., 12.9 ft. scribed "T30S R1W S 3 CS BT on a double blaze.
A 6" G.Fir bears N.67°30'W., 25.0 ft. scribed "T30S R1W S4 CS BT" on a double blaze. Placed County BT signs on both trees.

Corner lies 500 ft. south of F.S. Road No. 2929. The corner for Secs. 9 and 10 only bears N.87°E., 167.2 ft. (Rec. East, 165.0 ft.)