

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor. Secs 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 73 dated June 8, 1857 - (DCSO Records Vol 16 Pg 6668

Set post corner secs. 9, 10, 15, & 16, from which
An Oak, 18" dia., bears S.25°W. 52 lks.
An Oak, 18" dia., bears N.60°W. 70 lks.
An Oak, 20" dia., bears N.53°E. 97 lks.
An Oak, 10" dia., bears S.82°E. 83 lks.

GLO corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 16 Page 6695)

The corner of secs. 9, 10, 15, & 16 bears N 30 lks. This corner is partly obliterated. The post is greatly decayed & marks on BTs are deeply overgrown. I re-establish the corner in its orig. position as follows, destroying the old marks. Set a basalt stone 24x12x8" in mound of stone for corner of secs. 9, 10, 15, & 16, marked with 4 notches on S & 3 notches on E edge; from which
A B.Oak, 30" dia., bears N.56°E., 100 lks. mkd: T30S R1W S10 BT
A R.Fir, 7" dia. bears S.8°E. 32 lks. mkd: T30S R1W S15 BT
A B.Oak, 18" dia., bears S.23°W., 53 lks., mkd: T30S R1W S16 BT
A B.Oak, 20" dia. bears N.63°W. 70 lks mkd: T30S R1W S9 BT

Douglas Co. Surveyors Office - Frank Cain, Deputy - Recorded by F.C. Frear, Co. Surveyor - Nov. 24, 1920 - FB 107 Pg 70

Renewed & post set from which
A pine 36" dia., bears S.40½°E., 51 lks.
A Fir 10" dia., bears N.89½°E., 59 lks.
No trees in West, all burned.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & W. Penley - Feb. 1968 - C.S. File 54/59-77

Found - Frank Cain's 1920 renewal
36" now 42" Pine, S.40°E., 33.7 ft. shows scribe "R"
10" now 18" Fir, N.89½°E., 38.9 ft. shows face.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T30S R1W
OFFICE S 9|S 10
1968 S 16|S 17
Rescribed - 42" Pine S.40°E., 33.7 ft. mkd: T30S R1W S15 CS BT
New BTs- 12" Y.Pine S.59°W., 24.6 ft. mkd: T30S R1W S16 CS BT
12" S.Pine N.59°W., 36.4 ft. mkd: T30S R1W S9 CS BT
Note - This corner lies in N & S fence line.

FD. Ok by B. Shaner, 7/1999 - C.S. File 65/23-15 & M132-9