

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by Dennis Hathorn, US Deputy Surveyor under contract 73 dated June 8, 1857 - (DCSO Records Vol 16 Pg 6673

Set ¼ sec. post, from which
A pine, 24" dia., bears N.27°W. 32 lks.
A pine, 18" dia., bears S.89°W. 30 lks.

GLO corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 16 Page 6696)

This corner is nearly obliterated. The old corner which was a post has disappeared and marks on BTs are deeply overgrown. I re-establish the corner in its orig. position as follow:
Set a basalt stone 14x10x5" 9½" in the ground for ¼ sec. corner, marked ¼ on N face; from which
A R.Fir, 8" dia., bears N.42°E., 42 lks., mkd: ¼ S10 BT.
A R.Fir, 10" dia., bears S.52°W., 50 lks., mkd: ¼ S15 BT.

Reported as not fd by Frank Jones, DCSO 6/1968: I find no trace of this corner due to a fir. C.S. File 54/59-98

Bruce Shaner - For: USFS - Jan. 1981 - RM 3-42

Set - Brass cap mkd: T30S R1W WM 1/4 S10 S15 RLS 430 1980
12" P.Pine BT, scribed ¼ S15 BT bears S.68°W., 51.6'
20" P.Pine BT, scribed ¼ S10 BT bears N.23°E., 33.3'

Fd. Ok By B. Shaner, 7/1999 - M132-9 & C.S. File 65/23-15