

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, (North)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 14 Page(s) 6060)

-----  
Set post and build stone mound, cor. sec. 34, 35, 2 and 3, from which

- A Fir 24" dia., bears N.80°W., 40 lks. dist.
- A Fir 18" dia., bears S.52°W., 55 lks. dist.
- A Fir 9" dia., bears N.77°E., 18 lks. dist.
- A Maple 6" dia., bears S.30°E., 37 lks. dist.

GLO resurvey by Fred Mensch, U.S. Deputy Surveyor - under Contract #757, dated Sept. 14, 1904 - (DCSO records Vol. 14 Page(s) 6067)

-----  
Cor. of secs. 2, 3, 34 and 35, which is nearly obliterated. The old cor. which was a post has disappeared but indistinct remains of the mound of stone still remain. The Fir and the Maple described as bearing trees in secs. 2 and 3 have fallen. The other trees are standing but the marks are nearly indistinguishable.

I destroy the old marks and re-establish the cor. in its original position as follows:

Set a basalt stone 15x10x4 ins., 10" in the ground for cor. of secs. 2, 3, 34 and 35, marked with 2 notches on E. and 4 notches on W. edges, from which

- A Red Fir 12" dia., bears N.69°E., 109 lks. dist. mkd. T29S R1W S35 BT.
- A Cedar 18" dia., bears S.82°E., 73 lks. dist. mkd. T30S R1W S2 BT.
- A W.Fir 24" dia., bears S.86°W., 91 lks. dist. mkd. T30S R1W S3 BT.
- A Maple 4" dia., bears N.37°W., 57 lks. dist. mkd. T29S R1W S34 BT.

GLO survey by Ernest P. Rands, Deputy Surveyor, under Contract #790, dated Oct. 18, 1909 - (DCSO records Vol. 14 Page(s) 6102 & 6104)

-----  
Page 6102

Intersect the cor. of secs. 2, 3, 34 and 35, which is a stone, 8x7x5 ins. above ground, firmly set, marked and witnessed as described by the Surveyor General.

Page 6104

I destroy all markings on the old bearing trees referring to secs. 34 and 35.

(Cont. Next Page)

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 2 & 3 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Thomas E. Shrum, Jr. - For: U.S. Plywood - June 1967 - C.S.  
File 55/106 and M 36-14

-----  
Found - W.Fir stump, 26", S.86°W., 59.2 ft.  
          30" Cedar stump, S.85°E., 39.40 ft.  
Set 2½" alum. cap, from which new BTs:  
      6" Fir S.56°E., 22.45 ft.  
      12" Fir S.27°W., 27.90 ft.  
      5" Fir N.20°W., 42.95 ft.

-----  
Dennis Gaylord, U.S.F.S. (Deputized by the DCSO) - Wit:  
Randal Lopez - Nov. 17, 1977 - C.S. File 59/42-17

-----  
Found - 2½" Alum. cap stamped "U.S. P.C. Prop. Cor. 1967 Do  
          Not Disturb T30S R1W 35 3 2 RE 4287"  
Orig. Cedar now a 32" stump bears S.85°E., 38.6 ft.  
          (Rec. 39.4 ft.) scribing visible "R1W S2 B" on a  
          partly healed blaze.  
8" D.Fir bears S.56°E., 22.5 ft. Has a single healed  
          blaze.  
15" D.Fir bears S.27°W., 27.0 ft. (Rec. 27.5 ft.)  
          Some scribing visible on nearly healed blaze.  
8" D.Fir bears N.20°W., 42.6 ft. (Rec. 42.95 ft.)  
          Scribing visible "5 BT T29S R1W".  
The original BT to the SW. is gone.  
I placed BT signs on all accessories.  
Did Not Renew.  
Corner lies on a very steep West slope.