

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 24 only, West

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, US Cadastral Engineer - Under special instructions dated June 7, 1922 - (DCSO records Vol. 16 Page(s) 6739-40)

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor. of sec. 24 only, with brass cap marked

1/4S24
1923

from which

- A fir, 16" dia., bears N.45°E., 73 lks., mkd: 1/4 S24 BT.
- A laurel, 15" dia., bears S.18°E., 45 lks., mkd: 1/4 S24 BT.

Fd. OK, by DCSO J. Powell, 12/29/1967 - C.S. File 54/59-18

Douglas Co. Surveyors Office - Stephen J. Flause, Deputy - T. Plouff - B. Stewart - Began: 9/15/1980 completed 3/7/1981 - C.S. File 61/19-11

Found - 1923 US GLO brass cap properly marked lying loose on ground near a 1" cement filled I.P. protruding 8" from the ground leaning north and firmly set. The buried portion of the I.P. is uncovered and the pipe is found to be bent as well as leaning north. The accessories found are measured from the bottom end of the monument pipe.

1923 16" now a 20" DBH D.Fir bears N.45°E., 48.2 ft. Tree has a well healed single blaze, no scribing visible.

A 15" now 25" DBH Madrone (laurel) bears S.18°E., 29.7 ft. Tree has faintly visible blaze scar we open and find clear face of old blaze and scribe marks (because of easy rotting nature of this tree species, we do not open to where scribing would be legible).

Because bearings and distances agree to the bottom of the pipe found, and old road work in the area probably disturbed the original positioning, the location of the bottom of the found 1" I.P. is referenced out, the pipe removed from the ground, straightened & the GLO brass cap reaffixed to the top. This monument then is placed back in the referenced position. Because of likelihood of the GLO brass cap again coming loose SET - A DCSO 2 1/2" Brass cap on a 1" by 30" I.P. is placed on the south edge of the above mentioned monument. BC is marked "Douglas County Surveyor" 1/4 S24 R1W 1980. Both monuments are firmly set, the GLO monument now protrudes 8 1/2" & the DCSO monument 7" from the ground

New BTs- A 31" DBH Cedar bears S.34 1/2°W., 92.8 ft. and is scribed "1/4 S24 CS BT" on a double blaze. **cont.**

TOWNSHIP 30 RANGE 01 POINT IDENTIFIER # 600337

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 24 only, West

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A 37" DBH D.Fir bears N.21°W., 51.1 ft. and is scribed "¼ S24 CS BT" on a double blaze. These new trees are tagged with DCSO BT tags noting corner is for Section 24 only.