

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 139700

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. for Sec. 31 only, T29-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6222)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for 1/4 cor. of sec. 31 only, with brass cap mkd: 1/4 S31
1917

from which

A Fir 20" dia., bears N.8°30'E., 19 lks. dist. mkd. 1/4 S31 BT.

A Fir 30" dia., bears N.32°30'W., 30 lks. dist. mkd. 1/4 S31 BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 1968 - C.S. File 54/73-33

Found - GLO brass cap, properly mkd. in 1917.
30" now 38" D.Fir N.32½°W., 19.8 ft., shows good scar.

20" D.Fir, now down, N.8½°E., 12.5 ft.

New BT - 20" D.Fir N.30°E., 25.1 ft. mkd. 1/4 S31 CS BT.

Fd. and used in BLM resurvey by Peter Peterson and Daniel Berry under Group #749, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14920)

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - June 24, 1985 - C.S. File 62/28-8

Found - GLO brass cap on an I.P., protruding 14" above ground, properly mkd., in 1917.

20" now 22" dia., D.Fir tipped out with covered face, center of root hole bears N.8½°E., 12.5 ft. (agrees w/original rec.)

30" now 38" dia. D.Fir with a well healed single blaze, bears N.32½°W., 19.8 ft. (agrees w/rec)

20" now 24" dia. D.Fir with a well healed single blaze, bears N.30°E., 25.1 ft. (agrees w/rec.)

New BTs- 7" Cedar double blaze, scribed "1/4 S31 CS BT", bears N.76 3/4°E., 9.7 ft.

5" D.Fir double blazed, scribed "1/4 S31 CS BT" bears N.60 3/4°W., 30.9 ft.

This corner is S.89°50'26"W., 88.18 ft. from N. 1/4 cor. of sec. 6, T30-2.