

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 179700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32 only, T29-2

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6221)

-----  
Set a porphyry stone 15x12x6 ins., 10" in the ground, for cor. of secs. 31 and 32, marked with 5 notches on E. and 1 notch on W. edge; from which  
A Fir 10" dia., bears N.6°30'E., 21 lks. dist. mkd. T29S R2W S32 BT.  
A Fir 20" dia., bears N.38°15'W., 54 lks. dist. mkd. T29S R2W S31 BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 1968 - C.S. File 54/73-34

-----  
Found - No trace of corner stone.  
10" now 15" D.Fir N.6½°E., 13.9 ft., shows good scar  
20" now 25" D.Fir N.38°W., 35.6 ft., scribe visible.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S R2W S 31 | S 32  
T 30 S S 6  
1968  
New BT - 11" D.Fir S.2°E., 18.8 ft. mkd. T30S R2W S6 CS BT.  
This corner lies 73.9 ft. West of cor. to secs. 5 & 6, T30-2

BLM resurvey by Peter Peterson and Daniel Berry under Group #749, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14918-19)

-----  
Intersect the cor. of secs. 31 and 32 only, perpetuated and recorded by the County in 1968, monumented with an iron post 1½" dia., firmly set, protruding 8" above ground with brass cap mkd in 1968  
from which the original bearing trees  
A Fir 17" dia., bears N.6½°E., 21 lks. dist., with healed blaze.  
A Fir 28" dia., bears N.38¼°W., 54 lks. dist., with no marks visible on opened blaze.  
and a bearing tree mkd. by the County in 1968  
A Fir 12" dia., bears S.2°E., 28 lks. dist., with no marks visible on pitched over blaze.  
and a new bearing tree  
A Fir 13" dia., bears N.70°W., 47 lks. dist., mkd. T29S R2W S31 BT.

Fd. DCSO BC & BTs by Troy Rambo, July 2002 M140-73