

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 only (North)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 15 Page(s) 6202) (Duplicate Pg. 6826)

-----  
Set a quartz stone 18x15x6 ins., 12" in the ground for cor. of secs. 5, 6, 31 and 32, mkd. with 5 notches on E. and 1 notch on W. edge, from which  
A Fir 30" dia., bears N.50°E., 75 lks. dist. mkd. T29S R2W S32 BT.  
A Fir 24" dia., bears S.27°E., 18 lks. dist. mkd. T30S R2W S5 BT.  
A Fir 30" dia., bears S.16°W., 46 lks. dist. mkd. T30S R2W S6 BT.  
A Fir 40" dia., bears N.65°W., 16 lks. dist. mkd. T29S R2W S31 BT.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6221)

-----  
Intersect the cor. of secs. 5, 6, 31 and 32, which is a quartz stone, firmly set, marked and witnessed as described by the surveyor general. I change this cor. to refer to secs. 5 & 6, T30S R2W only by destroying all marks referring to secs. 31 and 32. From cor.  
A Fir 24" dia., bears S.27°E., 18 lks. dist., mkd. T30S R2W S5 BT. (Old BT)  
A Fir 30" dia., bears S.16°W., 46 lks. dist., mkd. T30S R2W S6 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 1968 - C.S. File 54/73-35

-----  
Found - 24" now 26" D.Fir S.27°E., 11.9 ft., shows good scar  
30" now 34" D.Fir S.16°W., 30.4 ft.  
Stone at sec. cor. (set) approx. size, no marks found.

Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S S 32  
T 30 S R2W S 6 | S 5  
1968

New BT - 8" Cedar N.34°E., 16.1 ft. mkd. T29S R2W S32 CS BT.  
This corner lies 73.9 ft. East of cor. for 31 & 32, T29-2

(Cont. Next Page)

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 only, (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Peter Peterson and Daniel Berry under Group #749, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14918)

-----

(Corner Report)

The Sec. cor., perpetuated and recorded by the County in 1968, monumented with an iron post 1½" dia., firmly set, protruding 8" above ground, with brass cap mkd. in 1968 from which the original bearing trees:

A Fir 43" dia., bears N.50°E., 75 lks. dist., with healed face (Strickler reported destroying the marks on this tree in 1917)

A Fir 25" dia., bears S.27°E., 18 lks. dist., with healed blaze.

A Fir 38" dia., bears S.16°W., 46 lks. dist., with healed blaze.

A Fir 53" dia., bears N.65°W., 16 lks. dist., with healed blaze. (Strickler reported destroying the marks on this tree in 1917)

and a bearing tree mkd. by the county in 1968:

A Cedar 10" dia., bears N.34°E., 25 lks. dist., with scribe marks T29S R2W S32 CS BT visible on open blaze.

Fd. BC & BTs by Troy Rambo, July 2002 M140-73