

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 240140

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Arthur R. Evans - May 1951 - C.S. File 44/121

Location for corner determined by intersection of N-S and E-W centerlines.

Marked 16" Fir for corner. Blaze and scribe on E. side "C $\frac{1}{4}$ cor. S.32 C.S.". West side is line, South side proper distance.

Blaze and scribe BTs:

14" Cedar S.77°E., 5.2 ft. mkd. C $\frac{1}{4}$ S32 CS BT.

22" Cedar S.42 $\frac{1}{2}$ °W., 31.4 ft. mkd. C $\frac{1}{4}$ S32 CS BT.

Survey by Mark Smalley, L.S. #2354 - For: Roseburg Resources Co. - April 1995 - M 121-77

Found - Badly rotted 20" fir stump corner tree

27" cedar S.77°E., 5.2'

22" cedar S.42 $\frac{1}{2}$ °W., 31.4', rotten stump

Set 5/8"x48" I.R. & alum. cap stamped L.S. 2354 in center of stump.

New BTs- 12" fir S.82°W., 22.8', "C $\frac{1}{4}$ BT"

7" fir N.24°E., 18.9', "C $\frac{1}{4}$ BT"

16" madrone N.88°E., 33.5' "C $\frac{1}{4}$ BT"

Fd Ok by Ken Hoffine 7/1999 M 133-1