

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5 only (North)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 15 Page(s) 6200-01) (Duplicate pgs. 6824-25)

-----  
Set a porphyry stone 18x10x8 ins., 12" in the ground for cor. of secs. 4, 5, 32 and 33, marked with 4 notches on E. and 2 notches on W. edge, from which  
A Maple 15" dia., bears N.54°E., 37 lks. dist. mkd. T29S R2W S32 BT.  
A Fir 30" dia., bears S.29°E., 6 lks. dist. mkd. T30S R2W S4 BT.  
A Cedar 12" dia., bears S.22½°W., 21 lks. dist. mkd. T30S R2W S5 BT.  
A Fir 12" dia., bears N.53½°W., 23 lks. dist. mkd. T29S R2W S32 BT.

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6219)

-----  
Intersect the cor. of secs. 4, 5, 32 and 33, which is a porphyry stone, firmly set, marked and witnessed as described by the surveyor general. I change this cor. to refer to secs. 4 and 5, T30S R2W only by destroying all marks referring to secs. 32 and 33. From Cor.  
A Fir 30" dia., bears S.29°E., 6 lks. dist., mkd. T30S R2W S4 BT. (Old BT)  
A Cedar 12" dia., bears S.22°30'W., 21 lks. dist. mkd. T30S R2W S5 BT. (Old BT)

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 21, 1968 - C.S. File 54/73-45

-----  
Found - No trace of stone at section corner.  
30" now 38" D.Fir S.29°E., 4.0 ft., shows good scar.  
12" Cedar now stob, S.22½°W., 13.9 ft., opened for scribe.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 29 S  
T 30 S R2W ¼ S 5 | S 4  
1968  
New BTs- 14" Hemlock S.64°W., 39.7 ft. mkd. T30S R2W S5 CSBT  
8" Fir N.34°W., 10.0 ft. mkd. T29S R2W S33 CS BT.  
This corner lies 62.7 ft. East of Secs. 32 & 33, T29-2

continued next page

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 300700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 4 & 5 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22647)

-----  
The cor. of secs. 4 and 5 only, on the N. bdy. of the Tp., perpetuated by the Douglas County Surveyor's Office in 1968, monumented with an iron post, 1½" dia. firmly set, projecting 15" above ground, with brass (properly) mkd. from which the remaining orig. bearing tree

A fir, 43" dia., bears S.29°E., 4.0 ft., with a healed blaze.

and BTs mkd. by the Douglas County Surveyor's Office in 1968

A hemlock, 19" dia., bears S.64½°W., 40.0 ft., with a healed blaze.

A fir, 11" dia., bears N.35°W., 9.8 ft., with a healed blaze.

Corner is located at the base of the westerly shoulder of a gravel road.

Ron Quimby - Crew: N. Fromdahl & R Heichel- 9/2018 - C.S. File 65/102-3

-----  
Found - DCSO brass cap (properly marked)  
44" D.Fir S.29°E., 4.0' good scar (Orig. BT)  
20" Hemlock S.64°W., 39.7 ft. good scar.  
10" Fir snag N.34°W., 10.0 ft. good scar.  
Brass cap S32|S33 only West 61.8 ft. (rec. 62.7)  
New - 10" Fir S.45°W., 40.0 ft scribed T30S R2W S5 BT  
Note - Corner is at toe of road fill.  
Compass decl. 15½°E.