

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15 & 16 only (North)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6854-55)

(At a point 310 lks. West of the cor. of secs. 9 and 10)

A Fir 10" dia., for closing cor. of secs. 15 and 16, I mark C C T30S R2W on S., S15 on E.; and S16 on W. face, with 4 grooves on S. and 3 grooves on E. face, from which
A Fir 12" dia., bears S.22½°E., 51 lks. dist. mkd. T30S R2W S15 BT.
A Fir 7" dia., bears S.33½°W., 40 lks. dist. mkd. T30S R2W S16 BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - Feb. 1960 - C.S. File 42/421-10

Determined by O.B.T.s:
12" Fir S.22°E., 33.7 ft.
10" Fir S.35°W., 26.4 ft., found scribe.
At corner point, found 12" Fir mkd. on 4 faces, and SET 3/4" x 30" Iron pipe, from which
10" W.Fir bears S.50°E., 14.4 ft. mkd. S15 X BT.
18" Cedar bears S.21°W., 47.0 ft. mkd. S16 R2W BT.

Fd. OK, DCSO R.Tracy, Oct. 11, 1968 - C.S. File 54/73-1A

Douglas County Surveyors Office - Gary L. Langlitz; M. Lenora Ladig - Dec. 17, 1975 - C.S. File 57/39-37

Found - Orig. 10" now 13" D.Fir Corner tree, alive with well healed blazes on S. E. and W. faces and 3/4" I.P. set at the base of the tree by Markham in 1960.
Orig. 12" now 15" D.Fir, bears S.22½°E., 33.7 ft., alive and well healed.
Orig. 7" now 11" D.Fir, alive and well healed, bears S.33½°W., 26.4 ft.
Markham BT, a 10" now 11" Grand Fir, scribe visible on partially healed blaze, bears S.50°E., 15.5 ft. (Rec. S.50°E., 14.4 ft.) (14.4 ft. dist. matches from pipe to BT)
Markham BT, a 18" now 15" I.Cedar, scribing visible on partially healed blaze, bears S.21°W., 47.0 ft.

This corner is located at a corner of fences running S. and E. approx. 600 ft. West of BLM Dompier Creek Rd.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15 & 16 only (North)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22657)

The cor. of secs. 15 and 16 only, perpetuated by Markham, Jr., in 1960, subsequently perpetuated by the Douglas County Surveyor's Office in 1975, monumented with the orig. cor. tree, a fir, 22" dia., with numerous healed blazes, wrapped with barbed wire, (alongside of which is an iron pipe, 24" long, 1½" dia., out of the ground), from which the remains of the original bearing trees

A sawed fir stump, 15" dia., bears S.18°E., 31.6 ft., with no marks visible on a partially healed blaze and metal cover. (Record, S.22½°E., 33.7 ft.)

A fir, 19" dia., bears S.38½°W., 26.4 ft., with a healed blaze. (Record, S.33½°W.)

and a bearing tree mkd. by Markham, Jr.

A fir, 14" dia., bears S.49°E., 12.9 ft., with no marks visible on a partially healed blaze.

A cedar, 20" dia., bears S.22½°W., 46.8 ft., with a healed blaze.

and new accessories

A rebar, 30" long, 5/8" dia., driven 26" in the ground for a reference monument, bears S.64°39'07"E., 16.00 ft., with an aluminum cap mkd. RM S15 16.0 FT TO COR T30S R2W 2008 and an arrow pointing to the corner.

A rebar, 30" long, 5/8" dia., driven 26" in the ground for a reference monument, bears S.28°00'28"W., 14.00 ft. with an aluminum cap mkd. RM S16 14.0 FT TO COR T30S R2W 2008 and an arrow pointing to the cor..

Corner is located at the intersection of barbed wire fences extending S., E., and W.