

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9 & 10 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #782, dated Dec 1, 1908 - (DCSO records Vol 16 Pages 6829-30)

Set a basalt stone 15x10x6 ins., 10" in the ground for cor. of secs. 9 & 10, marked with 3 notches on E. edge, from which
A Fir 48" dia. bears N.60°E., 26 lks. mkd. T30S R2W S10 BT
A Cedar 30" dia., bears N.70°W., 34 lks mkd T30S R2W S9 BT

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: O.A. Keatley - Feb. 1960 - C.S. File 42/421-11

Determined by O.B.T.s:
36" Cedar N.70°W., 21.0 ft., found scribe.
53" Fir N.60°E., 18.5 ft.
At corner point, found stone and SET 3/4" x 30" Iron pipe, from which
9" W.Fir S.38°E., 15.0 ft. "S15 BT"
12" W.Fir S.64°W., 21.6 ft. "S15 BT"
7" Cedar N.7°W., 23.0 ft. "S9 R2W BT"

Fd. OK, DCSO, R. Tracy, Oct. 11, 1968 - C.S. File 54/73-1A

Douglas Co. Surveyors Office - Clell Goodwin; Gary Langlitz; Vic Cangie; Lenora Ladig - Dec. 17, 1975 - C.S. File 57/39-36

Found - 3/4" x 30" I.P. and a 15"x10"x6" stone with 3 notches on E. side buried alongside.
Orig. 30" Cedar now a 36" I.Cedar, bears N.70°W., 21.0 ft.
Orig. 48" Fir, now a 53" D.Fir stump, bears N.60°E., 18.5 ft.
11" G.Fir with visible scribe marks bears S.38°E., 15.0 ft. (Markham)
14" G.Fir, well healed, bears S.64°W., 21.6 ft.
9" I.Cedar with visible scribed marks, bears N.7°W., 23.0 ft. (Markham)

Set 1" x 30" Iron pipe with brass cap stamped:

Douglas Co. Surveyor

T 30 S R 2 W

S 9 | S 10

S 15

1975

Set the found pipe to the South and the stone to the North of the corner.

Corner lies 400+ ft. West of Dompier Cr. Rd. in a fence running E-W.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9 & 10 only (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2232, Surveyed Oct. 2008/April 2009 - (DCSO records Vol. 57 Page(s) 22660-1)

The cor. of secs. 9 & 10 only, perpetuated by Markham, Jr., in 1960, subsequently perpetuated by Douglas County Surveyor's Office in 1975, monumented with an iron post, 1¼" dia., firmly set, projecting 7" above ground, (alongside of which is an iron pipe, 1½" dia., firmly set, projecting 6" above ground) with brass cap (properly) mkd.

from which the remains of the orig. bearing trees

A sawed fir stump, 46" dia., bears N.60°E., 17.2 ft., with a healed blaze.

A sawed, decayed cedar stump, 36" dia. bears N.70°W., 22.4 ft., with a hollow blaze and an X hacked in the bark. and the remains of bearing trees mkd. by Markham, Jr.

A fir, 21" dia., bears S. 64°W., 21.9 ft., with a healed blaze.

A roothole bears N.7½°W., 22.1 ft., alongside of which is a down, decayed cedar snag, size indeterminate, with a hollow blaze.

and new bearing trees

A fir, 7" dia. bears N.46¾°E., 6.8 ft mkd. T30S R2W S10 BT

A fir, 6" dia. bears N.65¾°W., 10.4 ft mkd T30S R2W S9 BT

Corner is located on a broken SE. slope, 0.8 ft. S. of a barbed wire fence line, bears E. and W.