

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 539700

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. Sec. 35 only, T29-2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6215-16)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for 1/4 cor. of sec. 35 only, with brass cap mkd. 1/4 S35
1917

from which

A Fir 15" dia., bears N.56°30'E., 69 lks. dist. mkd. 1/4 S35 BT.

A Balsam Fir 15" dia., bears N.51°15'W., 58 lks. dist. mkd. 1/4 S35 BT.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage & W. Penley, crew - Nov. 1968 - C.S. File 54/73-24

Found - 15" now 22" D.Fir N.56 1/2°E., 45.5 ft., shows good scar.

15" now 22" W.Fir N.51°W., 38.3 ft., opened for scribing.

No trace of 1917 brass cap as corner falls in cut for old skid road which comes directly down section line.

Set Brass cap at cor. mkd: County Surveyors Office
T 29 S R2W 1/4 S 35
T 30 S 1968

All bearing trees in good condition and tagged.

This corner lies 39.1 ft. West of 1/4 cor. Sec. 2 only, T30-2