

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6755)

-----  
Set post cor. secs. 25, 26, 35 and 36, from which  
A Fir 18" dia., bears S.88°W., 15 lks.  
A Fir 15" dia., bears N.75°W., 18 lks.  
A Fir 30" dia., bears N.60°E., 13 lks.  
A Fir 18" dia., bears S.30°E., 66 lks.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - Oct. 25, 1968 - C.S. File 54/73-12

-----  
Found - 30" now 38" D.Fir, N.60°E., 8.6 ft., shows good scar  
18" D.Fir, now stump, S.30°E., 43.6 ft., opened for  
scribe "BT".  
No trace of NW. or SW. BTs, skid road.  
Unrecorded D.Fir, now stump 5 ft. high, 1.0 ft.  
North of corner, faint bark scribe on SE. side,  
"T30S R2W S36", possible start of corner tree,  
then not used.

Set Brass cap at cor. mkd: County Surveyors Office  
T 30 S R 2 W  
S 26 | S 25  
S 35 | S 36  
1968

New BTs- 6" Y.Pine S.74°E., 33.4 ft. mkd. T30S R2W S36 CS BT  
13" D.Fir S.3°E., 20.9 ft. mkd. T30S R2W S36 CS BT.  
13" D.Fir N.59°W., 73.5 ft. mkd. T30S R2W S26 CS BT.  
No good trees close in Southwest.

Survey by Loyd R. Moffit, LS #944 - For: U.S. Forest Service  
April 1985 - C.S. File 63/8-3

-----  
Found - A 2½" brass cap on a 1" pipe, exposed 12".  
A 22" Fir stump, bears N.15°W., 1.7 ft.  
A 16" Fir bears N.59°W., 73.5 ft., scar visible.  
A 12" Pine bears S.74°E., 33.4 ft., scar visible.  
A 16" Fir bears S.03°E., 20.9 ft., scar visible.  
A 38" Fir bears N.50°E., 9.0 ft., no scar.  
A 16" Fir bears S.43°W., 39.5 ft., scribe visible.  
(No record)  
New BT - A 4" Fir which bears N.30°W., 18.0 ft. mkd. X BT.