

TOWNSHIP 30 RANGE 02 POINT IDENTIFIER # 639700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 36 only, T29-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Elmer F. Strickler, U.S. Transitman, under Special Instructions dated Jan. 22, 1917 - (DCSO records Vol. 15 Page(s) 6214)

Set an iron post 3 ft. long, 1" dia., 26" in the ground for 1/4 cor. of sec. 36 only, with brass cap mkd. $\frac{1}{4}$ S36
1917

from which

A Fir 10" dia., bears N.44°45'E., 18 lks. dist. mkd. $\frac{1}{4}$ S36
BT.

A Fir 14" dia., bears N.37°W., 47 lks. dist. mkd. $\frac{1}{4}$ S36
BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & W. Penley, crew - Oct/Nov. 1968 - C.S. File 54/73-28

Found - GLO brass cap, properly mkd., in 1917.
10" now 12" D.Fir N.45°E., 11.9 ft. shows scar, badly scared by logging.
14" now 17" D.Fir N.37°W., 31.0 ft. shows good scar.
New BT - 16" W.Fir N.51°E., 23.1 ft. mkd. $\frac{1}{4}$ S36 CS BT.
This corner lies 25.7 ft. West of 1/4 cor. Sec. 1, T30-2

Survey by Loyd R. Moffit, LS #944 - For: U.S.F.S. - Oct. 1986 - C.S. File 62/30

Found - 1917 GLO brass cap on a 1" Iron pipe.
A Fir stump bears N.37°W., 31.7 ft. (to center of tree), scar visible. (1917)
A 17" Fir bears N.45°E., 11.9 ft. scars visible. (1917)
A rotted Fir stump which bears N.51°E., 23.1 ft. old face visible.
New BT - A 12" Fir which bears N.38°E., 31.9 ft. scribed $\frac{1}{4}$ S36 BT with L.S. washer 944 nailed to BT scribe.

Fd. & used on BLM dependent resurvey by Wayne Rogers, Cadastral Surveyor and Robert Browning, under Group #1883 surveyed June & July 1998 - (DCSO recs. Vol. 53 Pg(s) 20330)