

PRIMARY CORNER DESCRIPTION C C for Secs. 25 and 36 only, T30-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William F. Briggs, U.S. Deputy Surveyor, under special instructions dated Aug. 7, 1891 - (DCSO records Vol. 17 Page(s) 7099-7100)

-----  
Set a Fir post, 4½ ft. long, 4" sq., 24" in the ground, on Thiel survey, marked T30S R4W S25 on NW.; CC S36 on SW.; CC with 5 notches on N. edge and 1 notch on S. edge, for cor. to secs. 25 and 36, from which

A Red Fir 8" dia., bears N.46½°W., 34 lks. dist. mkd. T30S R4W S25 BT CC.

Red Fir 12" dia., bears S.48°W., 33 lks. dist. mkd. T30S R4W S36 BT CC.

Ben B. Irving, Deputy Co. Surveyor - Wit: J.I. Irving; V.N. Poole,- March 19, 1930 - C.S. File 37/18 and M 1-37

-----  
Location identified from original BTs as recorded. Original post rotted off but on ground. Set new post properly marked, 3" x 36".

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel crew - March 1963 - C.S. File 52/138-49

-----  
Found - Orig. BT, 12" now 24" Fir, S.48°W., 21.7 ft., shows good scars and good bark scribing, not old.

Orig. 8" now 12" Fir stump section, N.46½°W., 22.4 ft., shows old axe work.

Set Brass cap at cor. mkd: County Surveyors Office

S 25 | T30S  
R4W S 36 | R3W

New BT - 14" R.Fir bears N.1°W., 40.8 ft. scribed S25 T30S R4W CS BT.

Douglas Co. Surveyors Office - S.J. Flause and T. Plouff, crew - March 26, 1981 - C.S. File 61/19-18

-----  
Found - 1963 2½" DCSO brass cap on a 1" I.P. firmly set and protruding 15" from the ground. Cap is properly marked.

An orig. Red Fir 12" now a 24" DBH D.Fir snag approx. 45 ft. tall, bears S.48°W., 21.8 ft. Tree has blaze scars an "X", blaze in the bark on the NE. side, and is bark scribed "T30 R4W S36 BT".

An orig. Red Fir 8" now a 10" dia., 30" tall rotted Fir stump, bears N.46½°W., 22.4 ft. Stump has old axe work, no scribing found.

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 100146

PRIMARY CORNER DESCRIPTION C C for Secs. 25 and 36 only, T30-4

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A 14" R.Fir now a 14" DBH D.Fir snag approx. 12 ft. tall bears N.01°W., 40.8 ft. Tree has unhealed double blaze mkd. T30S R4W S25 CS BT. (Rec. S25 T30S R4W CS BT)  
Monument position is accepted.  
New BTs -A 6" DBH D.Fir bears S.51½°W., 31.0 ft. and is scribed "T30S R4W S36 CS BT" on a double blaze.  
A 7" DBH D.Fir bears S.65°W., 61.2 ft. and is scribed "T30S R4W S36 CS BT" on a double blaze.  
The 14" Fir and the new BTs are tagged with DCSO BT tags.

Cor. used in BLM Administrative survey in 1981 - See BLM for information.

David Edwards - For: Rome Creek Timber LLC - Sept. 2011 - M162-72  
-----  
A BLM Administrative survey... dated 1981 by Bill May established the NE cor. of sec. 36  
Set true closing cor. 1981 Admin survey BTs:  
Found - 18" Fir N.69½°E., 11.9'  
15" Fir N.67°W., 20.5'  
Both w/healed blaze.  
Set - 5/8"x30" steel rebar with 2½" dia., alum. cap as per 2009 BLM Manual & Mkd. "LS 2339" and "ROSEBURG RESOURCES COMPANY" and "2011"  
6' steel post 2' west.

CC BC (DCSO per BLM admin survey) bears N.89°00'42"E 54.91' with the following BTs:  
18" Fir, S.51½°W., 31.0'  
24" Fir S.65°W., 61.2'  
Both with healed blaze.