

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6873)

Set ¼ sec. post, from which
A B.Oak 10" dia., bears S.80°W., 50 lks. dist.
A B.Oak 12" dia., bears S.62°E., 13 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 16 Page(s) 6903)

The ¼ sec. cor. post is gone, but both bearing trees are standing. I restore this cor. by setting a W.Oak post, 3 ft. long, 3" sq., 24" in the ground, mkd. ¼ S. on W. face, from which

A B.Oak 14" dia., bears S.80°W., 50 lks. dist. mkd. ¼ S BT
A B.Oak 16" dia., bears S.62°E., 135 lks. dist. mkd. ¼ S BT.

These are the old bearing trees whose marks I renew.

Ben B. Irving, Deputy Co. Surveyor - Wit: Ophir Perdue - Oct. 7, 1938 - M1-3 & C.S. File 37/133

Original BT, a B.Oak S.80°W., 50 lks., badly decayed. Orig. BT, a B.Oak S.62°E., 135 lks. not chopped out, in good condition. Set new BT:

A 12" Oak N.25°E., 69 lks. blazed and scribed ¼ S6 CS BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - Feb. 1963 - C.S. File 52/13824

Found - Orig. 12" now 24" B.Oak S.62°E., 89.1 ft. We open and find good scribing "¼".

Orig. SW BT, down and rotted and in slide area.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W

West ¼ S 6

1963

New BTs -10" W.Oak bears N.27°E., 5.0 ft. scribed W¼ S6 CS BT

7" W.Oak bears S.32°E., 15.5 ft. scribed W¼ S6 CS BT