

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6 (NW Tsp Corner)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 15 Page(s) 6299)

Set a post, cor. of secs. 1, 6, 31 and 36, from which
A B.Oak 10" dia., bears S.78°E., 50 lks. dist.
A B.Oak 8" dia., bears N.85°E., 65 lks. dist.
A B.Oak 6" dia., bears S.40°W., 59 lks. dist.
A B.Oak 8" dia., bears N.47°W., 49 lks. dist.

Corner used and tied in GLO survey by Dennis Hathorn, Contract #73 dated June 8, 1857 (DCSO records, Vol. 15 Page 6309)

Fd. and used in GLO survey by W.H. Byars, Deputy Surveyor, under contract #376, dated Jan. 22, 1881 (tied April 13, 1881) - (DCSO records Vol. 15 Page 6317)

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 15 Page(s) 6399) and (Vol. 16 Page 6902)

(Vol. 15 Pg. 6399)
At the corner to Tps. 29 and 30 S., Rs. 3 and 4 W., which is a Cedar post, 4" sq. marked: T29S S31 on NE.; R3W S6 on SE.; T30S S1 on SW.; R4W S36 on NW. faces, with 6 notches on each edge.
(Vol. 16 Pg. 6902)
The post for this corner is lying down, partially decayed, but all bearing trees are standing. I restore this cor. by setting a Cedar post, 4½ ft. long, 4" sq., 24" in the ground, mkd. T29S S31 on NE.; R3W S6 on SE.; T30S S1 on SW.; R4W S36 on NW. faces, with 6 notches on each edge, from which
A B.Oak 12" dia., bears S.78°E., 50 lks. dist. mkd. T30S R3W S6 BT.
A B.Oak 10" dia., bears N.85°E., 65 lks. dist. mkd. T29S R3W S30 BT.
A B.Oak 10" dia., bears S.40°W., 59 lks. dist. mkd. T30S R4W S1 BT.
A B.Oak 12" dia., bears N.47°W., 49 lks. dist. mkd. T29S R4W S36 BT.
These are the old bearing trees whose marks I renewed.

Douglas Co. Surveyors Office - Ben B. Irving, deputy - Wit: Wm. Crear; R.L. Irving - Feb. 28, 1928 - C.S. File 37/133 (and "old" corner book, Page 200)

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6 (NW Tsp. Corner)

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Identified by old rotted stake, down and bearing faint scribe marks and original BTs. OBT in section 36 down and rotting. BT in sec. 31, broken off and dead. BT in sec. 1, dead and BT in sec. 6 alive but blazes having been chopped out are badly rotted.

Set a Cedar post 4" x 6" x 12" for corner scribed T29S S31 on NE. face; R3W S6 on SE. face; T30S S1 on SW. face; R4W S36 on NW. face.

New BTs as follows:

- A 15" B.Oak N.60°5'W., 45.5 lks. scribed T29S R4W S36 CSBT
- A 12" Fir N.53°E., 29.8 lks. scribed T29S R3W S31 CS BT.
- Orig. BT, a 14" B.Oak S.79°20'E., 47.7 lks., not chopped out or remarked.
- A 14" B.Oak S.84°10'W., 61 lks. scribed T30S R4W S1 CS BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Nov. 1, 1962 - C.S. File 52/126-75

Found - 4"x4"x6.0 ft. scribed Cedar post at corner.
 14" B.Oak S.84°W., 40.3 ft., shows rotted face.
 12" now 16" R.Fir N.53°E., 19.7 ft., shows good scar
 No other BTs found.

Set Brass cap at cor. mkd: County Surveyors Office

R4W	S36	S31	R3W	T29S
	S 1	S 6		T30S
	1962			

New BTs -10" R.Fir bears N.71°W., 38.0 ft. scribed S36 T29S R4W CS BT.
 7" Cedar bears S.55°W., 31.9 ft. scribed S1 CS BT.
 No trees near to SE.
 Fence corner bears N.35°W., 11.5 ft. from brass cap. Fences running North and West.

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #554 - Surveyed July 1964/April 1965 - (DCSO records Vol. 33 Page(s) 13785-86)

The cor., perpetuated and recorded by Irving in 1928, from the remains of the original bearing trees, which are no longer in existence; subsequently remonumented by Byron in 1962 with an iron post, 1" dia., 18" above ground, firmly set, with mkd. brass cap

from which bearing trees mkd. by Irving:

- A Fir 15" dia., bears N.52 3/4°E., 29½ lks. dist. with a healed blaze and cruiser mark "M".
- An Oak snag 18" dia., bears S.82°W., 61½ lks. dist. with a rotted blaze.

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 100700

PRIMARY CORNER DESCRIPTION NW Cor. Sec. 6 (NW Tsp. cor.)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An Oak stump hole bears N.61½°W., 45 lks. dist.
and bearing trees mkd. by Byron:
A Cedar 9" dia., bears S.52°W., 48 lks. dist. mkd. S1 CS
BT on double blaze.
A Fir 12" dia., bears N.74¼°W., 56 lks. dist. mkd. T29S
R4W S36 CS BT.
No other suitable trees available within limits.
Add the marks BLM to the brass cap.

James Klein & Richard Kitz - For: Pacific Connector Gas
Pipeline Project/Williams - Sept. 2014 - M166-19 A-E &
revised map M166-45 A

Found - 2½" brass cap stamped County Surveyor Office 1962
BTs - 22" Fir with BLM tag dated 8/57 N.52¼°E., 19.5'
13" Cedar set tag dated 11/13 S.23°E., 31.45' to
nail side center
8.2" Cedar set tag dated 11/13 S.36°W., 23.3' to
nail side center
16.5" Cedar set tag dated 11/13 N.78°W., 18.55' to
nail side center