

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 30 and 31

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6876)

Set ¼ sec. post, from which
A Fir 12" dia., bears S.88°E., 40 lks. dist.
A Cedar 24" dia., bears N.70°E., 40 lks. dist.
This ¼ sec. post was planted at 42 instead of 40 chs. to allow for the convergency of meridians, this being 17 miles S. of the standard parallel.

Douglas Co. Surveyors office - G.G. Stewart - Ben B. Irving, Deputy - Wit: V.N. Poole; J. Davenport - Dec. 15, 1921 - C.S. File 7/26 and Vol. 3 Pg. 100

Found Yew post scribed "¼". BTs gone. Location pointed out by V.W. Poole.
Set Iron pipe for corner. Marked new BTs:
A 16" Maple N.69°W., 24.0 ft.
A 30" Fir S.46°E., 60.0 ft.
Note: Found as noted - original BTs, one burned out, other down and rotting. Check OK. Ben B. Irving, D.C.S.

Survey for deed description, from Allen to Ray Spencer - April 3, 1937 by Boyer and Lane - C.S. File 30/11

Set 8"x6"x24" stone, white quartz. Original BTs.
16" Maple N.69°W., 24 ft.
30" Fir S.46°E., 60 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-19

Found - 30" Fir stump, shows bark scribing, S.46°E., 60.0 ft
16" now 26" Maple N.69°W., 24.0 ft., shows good scar
Do not find I.Pipe set by Stewart but we do find 1½" sq. head bolt SW. 1.0 ft. from corner.

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 3 W

¼ $\frac{S\ 30}{S\ 31}$
1963

New BTs- Rescribe now 26" Maple, N.69°W., 24.0 ft. "¼ S30 CS BT"
12" R.Fir bears S.36°E., 33.2 ft. scribed "¼ S31 CS BT."

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 30 and 31

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Bruce Shaner, L.S. #430 - For: Roseburg Forest Products - Feb. 1995 - M 119-52 - C.S. File 63/161-19

Found - 2½" brass cap on a 1" iron pipe.
30" D.Fir stump, bark scribe not visible, bears S.46°W., 60' to face.
28" Maple, face overgrown, bears N.69°W., 24.0'
1½" sq. head bolt, bears S.25°W., 1.3'.
12" D.Fir snag, badly rotten, bears S.36°E., 33.2'.
New BOs-14" D.Fir, scribed "¼ S31 BT" bears S.59°E., 18.6'.
6' steel fence post, North, 0.8'.
Poole Creek is S.45°W., 80.0' from corner.