

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6877)

Set 1/4 sec. post, from which
A Fir 12" dia., bears N.30°E., 25 lks. dist.
A Fir 12" dia., bears N.2°W., 23 lks. dist.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - Wit: J.A. Irving; V.N. Poole; Walter Poole; Roy Mathews - Feb/March 1930 - C.S. File 3-/41 and M 1-37

Location identified from original BTs. Set 6" x 6" x 48" Yew wood post for corner. Remark both BTs.

***Survey by Victor McLind - For: Murray and Washburn - May 1972 - M 42-63

Nothing found at 1/4 corner. Set by proportional measurement.

Set brass cap stamped: T30S R3W
1/4 S 30 S 29
RLS 934
1972

from which

A 10" Cedar scribed "T30S R3W 1/4 S30" bears West, 6.4 ft.
A 9" R.Fir scribed "T30S R3W 1/4 S29" bears S.82°E., 42.6 ft

***Survey by Bruce Shaner, L.S. #430 - For: Roseburg Forest Products - Feb. 1995 - M 119-52 - C.S. File 63/161-18

Found - 2 1/2" brass cap on a 1" iron pipe.
10" Cedar, burned & dead (snag), scribes visible, bears West, 6.4'.
12" D.Fir, now snag, face overgrown, bears S.82°E., 42.6'.

New BOs- Three 6 ft steel fence posts were set at 1.0', due North, South & East, from corner. (Land owner was not happy with the idea of scribing or marking the 2 trees available.

Corner is 30' N.15°E., from Ferguson Lane. Blue roofed barn is N.26°E., 350' from the corner.

1/4 Corner position determined from erroneously set section corner see 1988 DCSO renewal of the Cor. to secs. 29, 30, 31, & 32 (PLSS 200200) - 12/9/2004 Randy Smith, Deputy Co. Surveyor, DCSO.