

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO rec. Vol. 16 Page(s) 6879-80)  
-----

Set ¼ sec. post, from which  
An Oak 12" dia., bears N.50°E., 20 lks. dist.  
An Oak 18" dia., bears N.52°W., 20 lks. dist.

George Wenderoth -June/Aug. 1950 - C.S. File 45/91 & M 7-56A  
-----

Set 300 ft. South of Witness Corner on line to cor. 17,18,19 and 20. No BTs or sign of corner.  
Drive 1" I.Pipe, from which mark  
18" Fir S.14°40'W., 87.0 ft.  
All other trees dead.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Feb. 1963 - C.S. File 52/138-28  
-----

Found 1" I.P. at cor. and BT as recorded, shows good scribing on stump section.  
New BT - 6" R.Fir bears N.19°E., 17.7 ft. scribed ¼ S17 CS BT

Survey by John H. Markham, Jr. - For: C & D Lumber Co. - April/May 1989 - M 101-53  
-----

Found 1" iron pipe bent over badly. Reset brass cap at point and set the pipe on the South side of cap. Original bearing trees have been destroyed. Marked two new bearing trees.  
Set Brass cap mkd. "LS 1261 ¼ T30S S18 S17 R3W 1989", from which  
A 12" D.Fir bears N.35½°W., 18.7 ft. mkd. ¼ S18 BT.  
A 14" D.Fir bears N.63½°E., 27.1 ft. mkd. ¼ S17 BT.  
Fence corner bears South 17.5 ft.

BLM Dependent resurvey by Timothy Moore, Cadastral Surveyor & Robert Browning, Surveying Technician under Group #1952, surveyed June. 2000. (DCSO rec. Vol. 53 page(s) 20713-4)  
-----

The ¼ sec. cor. of secs. 17 & 18, reestablished by Wenderoth, in 1950, recovered & perpetuated by Byron, in 1963, further perpetuated by Markham, in 1989. This point was reestablished from the correct control, was utilized for the subdivision of section 18, has been relied upon for over 50 years, and is accepted as the corner. Monumented with an iron pipe, 2" diam., firmly set, projecting 3" above ground, with brass cap properly mkd.  
from which bearing trees mkd. by Markham  
continued next page

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 18" dia., bears N. 63½° E., 27.2 ft., with a healed blaze.

A fir, 12" dia., bears N. 35½° W., 18.9 ft., with a healed blaze.

From this point, Wenderoth's iron pipe, 1" dia., disturbed and badly bent, bears South, 0.65 ft.

From this same point, U.S. Geological Survey triangulation station BLAND MTN, bears N. 83° 05' 50" W, 4920.35 ft. (mean bearing and sea level distance), monumented with a bronze disk, cemented flush in solid rock, with top mkd. "BLAND MTN 1953" and a triangle.

Corner is located N. 5° E., 17.0 ft., from a cor. of barbed wire fences extending south and west.

Fd. & used on BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2000, 2100, & 2300, surveyed Nov. 2004/Feb. 2005 - (DCSO rec. Vol. 55 Page(s) 21501-4) & Plat 2008-1