

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6 only, (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6889)

-----  
Set post cor. secs. 5, 6, 7 and 8, from which  
A Maple 6" dia., bears N.60°W., 28 lks. dist.  
A Maple 6" dia., bears S.30°W., 17 lks. dist.  
A Fir 30" dia., bears N.80°E., 65 lks. dist.  
A Fir 30" dia., bears S.40°E., 32 lks. dist.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6973-74)

-----  
The Sec. cor., which is a post, greatly decayed with marks obliterated. I remove this post cor. and set a stone 12x8x8 ins., 8" in the ground for cor. to secs. 5 and 6 marked with 5 notches on E. and S. edges, from which  
A Fir 30" dia., (36" now) bears N.80°E., 65 lks. dist. mkd. T30S R3W S5 BT.  
A Fir 30" dia., bears S.40°E., 32 lks. dist., mkd. T30S R3W S8 BT.  
A Maple 6" dia, bears S.30°W., 17 lks. dist. mkd. T30S R3W S7 BT.  
A Maple 6" dia., (10" now) bears N.60°W., 28 lks. dist. mkd. T30S R3W S6 BT.  
As this is not a cor. to secs. 7 and 8, I destroy the marks on the Maple and Fir trees S. of this cor. which refer to secs. 7 and 8.

Douglas Co. Surveyors Office - Ben B. Irving, Deputy - Wit: Lew Smick; Louis Gilboa - March 24, 1928 - C.S. File 14/29

-----  
Location identified from three original BTs and stump of fourth which conforms to original field notes as recorded. Drove a Yewwood post 3" x 3" x 36" for corner scribed S6|S5 T30S R3W CS.

Survey by John H. Markham, Jr. - Fred Seymour, Witness - March 16, 1951 - C.S. File 40/302

-----  
At corner point, found 4" x 4" wood post scribed. Both Fir BTs standing and in good condition. At corner point, Set 1" x 24" Iron pipe, from which  
A Maple 12" dia., bears S.46°W, 14.5 ft. mkd. S8 BT.  
Sec. cor. for 7 \* 8 bears West 408.5 ft.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec Cor for 5 & 6 only, (South)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Feb. 1963 - C.S. File 52/138-30

-----  
Found Iron pipe at corner and 12" maple S.46°W., 14.5 ft. shows scribing.

Set brass cap at corner and alongside I.P. mkd. T30S R3W S6|S5 County Surveyors Office 1963.

New BT - 6" R.Fir bears N.49°E., 21.9 ft. scribed S5 CS BT. Corner at fence corner, fences running E-W and North.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #599, surveyed Sept. 1965 - (DCSO records Vol. 33 Page(s) 13908-09)

-----  
The cor. of secs. 5 and 6 only, on the N. bdy. of sec.8, perpetuated and recorded by Markham in 1951, monumented with an iron pipe 1" dia., firmly set, extending 12" above ground, subsequently remonumented by Byron in 1963, with an iron post 1" dia., firmly set, extending 16" above ground, with brass cap mkd. in 1963

from which the remaining original bearing trees;

A sawed Fir stump 40" dia., bears N.86°E., 65 lks. dist., with opened blaze, no marks visible. (Rec. N.80°E.)

A sawed Fir stump 36" dia., bears S.18°E., 32 lks. dist. mkd. T30S R3W S8 on opened blaze. (Rec. S.40°E.) The marks were reported destroyed by Bushey in 1893.

A Maple 15" dia., bears N.60°W., 28 lks. dist., with illegible scribe marks on opened blaze.

and a bearing tree marked by Markham:

A Maple 15" dia., bears S.46°E., 23 lks. dist., with healed double blaze.

and a bearing tree mkd. by Byron:

A Fir 8" dia., bears N.49°E., 33 lks. dist., mkd. S5 CS BT on double blaze.

Add the marks BLM 1965 to the brass cap.

Fd. OK by D. Edwards, Dec. 1999 - M133-66

Tony Hostetter - For: Roseburg Resources - 6/2006 - M151-9

-----  
Found - 1963 brass cap as described by J. E. Jelly (V. 33 Pg. 13908-9) accessories as described except:

8" Fir @ N.49°E., is gone

Maple listed @ S.46°E., is actually S.46°W.

New BT - 14" fir scribed "S5 SW BT" bears N.53°36'E., 13.2 ft