

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6880)

Marked a Fir 10" dia., for ¼ sec. cor., from which
A Fir 10" dia., bears S.7°E., 12 lks. dist.
A Fir 15" dia., bears N.70°E., 23 lks. dist.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. -
Wit: R.G. Boyed - June 9, 1960 - C.S. File 42/392-58

Determined by O.B.T:
20" Fir stump, logged, N.70°E., 15.2 ft.
At Corner point, Set 2" x 36" truck axle with flange up, from
which
24" Fir S.41°E., 122.0 ft. "¼ S32 BT"
14" Fir N.73°W., 59.0 ft. "¼ S29 BT"
A good rock road loops the corner. Road bears South 35.0 ft.
Road bears East 41.0 ft.

Douglas Co. Surveyors Office - Stephen Flause, Deputy - Bill
Stewart; Karen Mosely, crew - Sept. 11, 1980 - C.S. File
61/11-22

Found - A truck axle measuring approx. 1 3/4" in dia. (Rec.
2" x 36") and topped by a 5½" flange. Axle is
firmly set and buried approx. 1 ft. under soil
surface.

(Logging and road construction have removed evidence of
original BTs.)

A 24" now a 25" DBH D.Fir, bears S.41°E., 122.0 ft.
Tree has a well healed single blaze. No scribing
visible.

A 14" now a 17" DBH D.Fir bears N.73°W., 59.2 ft.
(Rec. N.73°W., 59.0 ft.) Tree has a well healed
single blaze with no scribing visible. This tree
is partially hidden by a young 5" D.Fir growing
between it and the monument. Both trees have
DCSO BT tags from Jan. 1963.

We judge discrepancy of measurement to NW. tree as being
reasonable and accept the position of the monument found as
being good.

New BTs- An 11" DBH D.Fir bears N.21½°W., 13.4 ft. and is
scribed "¼ S29 CS BT" in a double blaze.

An 11" DBH D.Fir bears S.86°E., 5.5 ft. and is
scribed "¼ S32 CS BT" on a double blaze.

Both trees are tagged with DCSO BT tags.

continued next page

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2000, 2100, & 2300, surveyed Nov. 2004/Feb. 2005 - (DCSO rec. Vol. 55 Page(s) 21501-4) & 2008-1 thru 2008-4 Plats

The ¼ sec. cor. of secs. 29 & 32, perpetuated by Markham in 1960 from orig. evidence no longer in existence, further perpetuated by Flause in 1980, a truck axle 36" long, 1¾" dia., lying on the ground at record bearing & dist. from the remains of BTs by Markham

A burnt fir stump, 25" dia., bears S.41°E., 122.0 ft. with scribe marks BT visible on open blaze.

A burnt fir stump, 17" dia., bears N.73°W., 59.0 ft. with no marks visible.

from which the remains of a BT mkd. by Flause

A burnt roothole bears N.21°W., 13.5 ft. no trunk remains.

At the corner point

Set an iron post, 28" long, 2½" dia., 20" in the ground, with brass cap marked:

T30S R3W
¼ S 29
 S 32
2004

from which

A rebar, 30" long, 5/8" dia., driven 30" in the ground for a reference monument, bears S.47½°W., 7.50 ft. with alum. cap mkd: RM ¼ S32 7.5 FT. TO COR. 2004 and an arrow pointing to the cor.

A rebar, 30" long, 5/8" dia., driven 28" in the ground for a reference monument, bears N.46°W., 7.50 ft. with alum. cap mkd: RM ¼ S29 7.5 FT. TO COR. 2004 and an arrow pointing to the cor.

Bury the axle inverted & deposit a magnet in a white plastic case at the base of the stainless steel post.

Fd. & used on BLM Dependent resurvey by Timothy J Moore, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2127 surveyed Feb/April 2006- (DCSO records Vol. 57 Page(s) 22519) - Corner is located 35 ft. N. of a graveled road, 16 ft. wide, which bears N.60°E. and S.74°W