

PRIMARY CORNER DESCRIPTION NE Corner Section 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCS0 records Vol 16 Pages 6965-66)

-----  
At point of intersection, Set a stone 14x6x6 ins., 10" in the ground, for closing cor. to secs. 8 and 9 marked CC on S. face with 4 notches on E. & 5 notches on S. edges, from which  
A Fir 9" dia., bears S.17¼°E., 26 lks. mkd. T30S R3W S9 BT  
A Fir 18" dia., bears S.34½°W., 33½ lks mkd. T30S R3W S8 BT  
A Fir 15" dia., bears N.23°E., 28 lks. mkd. T30S R3W CC 8 and 9 BT.

Survey by John H. Markham, Jr. - Wit: Fred Seymour; Bud Johnson; Wm. Markham; - Oct. 4, 1951 - C.S. File 40/381-2

-----  
Determined from OBTs  
A Fir 30" dia., bears S.34°W., 21.0 ft.  
A Fir 23" dia., bears N.23°E., 18.0 ft.  
I remarked both BTs.  
At the corner point, I found a large stone and Set a 1" x 30" Iron pipe, from which  
A Fir 17" dia., bears S.70°E., 9.0 ft. mkd. S9 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-6

-----  
Found - I.Pipe and stone at corner.  
Orig. now 24" R.Fir N.23°E., 18.0 ft., shows orig. scribe and Markham's bark scribing. I rescribe this BT "S5 T30S R3W CS BT"  
All other BTs dead. No other live trees near.

Survey by Bruce Shaner, PLS #430 - For: Longview Fibre Co. and C & D Lumber - Aug. 23, 1979 - M 79-2

-----  
Found 1" Iron Pipe.  
Set Brass cap alongside mkd. T30S R3W W.M. S5 S8 S9 CC PLS 430 1979, from which  
24" D.Fir, orig. BT, blowdown, scribes visible, bears N.23°E., 18.5 ft.  
30" D.Fir orig. BT stump, old face bears S.34½°W., 22.1 ft  
18" D.Fir BT by Markham, snag, scribes visible, bears S.70°E., 9.9 ft. (Rec. 9.0 ft.)  
8" D.Fir, I Scribe "T30S R3W S8 CC BT", bears S.87°W., 13.8 ft.  
8" D.Fir, I Scribe "T30S R3W S9 CC BT" bears S.32°E., 33.1 ft.

continued next page

PRIMARY CORNER DESCRIPTION NE Corner Section 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Fd. OK by D. Edwards, Dec. 1999 - M133-66

Douglas Co. Surveyor's Office - Crew: Stephen J Flause & Jeffery Lorsung - 9/13/2018 - C.S. File 67/45-22

-----

Found - A 2" i.d. iron pipe by Shaner in 1979, loosely set and leaning westerly projecting 13" above the ground with a 2½" brass cap (properly) mkd. I reset the iron pipe in a solid and plumb position.

Original BTs by W. Bushey in 1893:  
A rotted root ball in a root hole bears N.23°E., 18.5 ft.  
A 30"x2' tall D. fir stump bears S.34½°W., 22.1 ft.

Accessories by Markham in 1951  
A rotted D.Fir stump, S.75°E., 9 9 ft. (Record S.70°E.,)  
A 1" iron pipe, projecting 11" above the ground is set along the west side of the 2" iron pipe.

BTs by Shaner in 1979:  
A 14" D.Fir bears S.29½°E., 32.4 ft. with a healed blaze. (Record S.32°E., 33.1 ft.)  
A 21" D.Fir bears S.87°W., 13.8 ft. with a healed blaze.

New - A 14" D.Fir bears N.59°E., 3.6 ft. scribed "T30S R3W S5" "CSBT".  
A 14"x12" tall D.Fir stump bears N.28½°W., 20.7 ft. to a 8" galv. spike driven into the center of the stump.  
A found 6' galv. U-Post bears East, 2.0 ft.

LOCATION & COMMENTS:  
All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.  
Section corner is located approximately 200 ft. West of the access road.

COMPASS DECLINATION: 15°E.  
GEODETIC COORDINATES  
LATITUDE: 42°59'05.940" N. LONGITUDE: 123°04'51.955" W.  
DATUM: NAD 83, Epoch 2010.00  
SOURCE: Trimble GeoXT 6000