

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6884)

Set ¼ sec. post, from which
A Fir 12" dia., bears S.15°W., 28 lks. dist.
A Fir 18" dia., bears N.80°E., 13 lks. dist.

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6958-59)

The ¼ sec.cor. which is a post, greatly decayed, marked ¼ S. on W. face. I find the 2 witness trees. I remove this post and set a Cedar post, 4 ft. long, 4" sq., 24" in the ground, marked ¼ S. on W. face, from which
A Fir 12" dia., (18" now) bears S.15°W., 28 lks. dist., marked ¼ S BT.
A Fir 18" dia., bears N.80°E., 13 lks. dist. mkd. ¼ S BT.
This tree is marked in the bark, I mark it in the wood, "¼ S BT"

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: Geo. and Dennis Vaughn; Elmer Sutton - Jan. 26, 1951 - C.S. File 40/384-2

Determined by O.B.Ts:
A Fir 14" dia., bears S.16°W., 15.0 ft.
A Fir windfall, bears N.80°E., 8.0 ft.
At corner point, Set 1" x 30" I.P., from which
A Fir 30" dia., bears N.61°E., 20.0 ft. mkd. ¼ S BT.
A Laurel 8" dia., bears S.67°W., 55.0 ft. mkd. ¼ S S20 T30S R3W BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-9

Found 1" I.Pipe at corner and both BTs as recorded by Markham. NE. BT now down. We rescribe SW. BT "¼ S20 CS BT". Original 12" Fir S.15°W., 28.0 ft. is OK.
New BT - 10" Laurel N.56°E., 31.0 ft. "¼ S21 CS BT."

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1294, Surveyed May/June 1986 - (DCSO records Vol. 48 Page(s) 18231)

The ¼ sec. cor., perpetuated and recorded by Markham in 1951, and further perpetuated and recorded by Byron in 1963,
(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

monumented with an iron pipe 1" dia., firmly set, projecting 10" above ground, from which the remains of the original bearing trees:

A root hole bears N.80°E., 13 lks. dist., with a rooted Fir 15" dia., lying alongside, no visible marks.

A Fir 22" dia., bears S.15°W., 24 lks. dist., with healed blaze. (Record, 28 lks.)

and the remains of the bearing trees mkd. by Markham:

A root hole bears N.61°E., 24 lks. dist., with a rotted Fir 25" dia., lying alongside, no visible marks.

A Madrone 13" dia., bears S.75°W., 84 lks. dist., with illegible scribe marks on a partially healed blaze.

and a bearing tree mkd. by Byron:

A Madrone 13" dia., bears N.58°E., 48 lks. dist., with healed blaze.

At the corner point

Set an stainless steel post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 30 S R 3 W
1/4
S 20 | S 21
1986

Deposit iron pipe alongside and a white "DEEP-1" magnetic marker at base of stainless steel post.

Greg Lang - Oct. 2004 - C.S. File 65/52-13

Found - 3 1/2" BLM brass cap
23 1/2" D.Fir (orig.) bears S.15 3/4°W 15.30'
16 1/2" Madrone bears N.54 1/2°E., 30.10'
13" Madrone bears S.69 1/2°W., 54.50'

New - 9" D.Fir bears N.32 1/2°W., 9.80' scribed "1/4 S20 BT"
24" D. Fir bears S.19 1/4°E., 35.10' scribed "1/4 S21 BT"

NOTE - We set & measured to spikes in the base of all BTs; bearings to the trees are based on BLM's 1972 survey line from the N 1/4 Corner to the NW Section Corner of Section 21 (S.89°41'00"W).

Corner is located on a southerly slope just easterly of a small creek; corner also bears approximately N.86°E. 230'+/- from the end of a dirt road.