

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 21 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6883)

Set ¼ sec. post, from which
A Fir 6" dia., bears N.80°W., 23 lks. dist.
A Fir 6' dia., bears S.80°W., 24 lks. dist.

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6957)

The ¼ sec. cor. which is a post greatly decayed mkd. ¼ S on N. face. I remove this post and set a stone 11 x 10 x 5 ins., 7" in the ground for ¼ cor. marked ¼ on N. face, from which
A Fir 6" dia., (12" now) bears N.80°W., 23 lks. dist. mkd. ¼ S BT.
A Fir 6" dia., bears S.80°W., 24 lks. dist. mkd. ¼ S BT.

Survey by John H. Markham, Jr. - For: Stomar Lumber Co. - Wit: Wit: Ivan Kelly - Oct. 18, 1951 - C.S. File 40/384-1

Determined by O.B.T:
A Fir 12" dia., bears S.80°W., 14.7 ft. dist. I remarked this original BT.
A dead Fir windfall 8" dia., bears N.80°W., 15.2 ft. (OBT)
At corner point, found original stone and Set I.P., from which
A Laurel 14" dia., bears N.71°W., 29.6 ft. mkd. ¼ S. S21 T30S R3W 2880 BT.
A Laurel 13" dia., bears S.44°E., 17.6 ft. mkd. ¼ S S28 T30S R3W 2880 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-39

Found - Stone at corner and orig. SW. BT and both BTs as recorded by Markham.
Do not find pipe at corner.
Set brass cap alongside corner stone, mkd:
County Surveyors Office
¼ $\frac{S\ 21}{S\ 28}$ T30S R3W
1963
No new bearing trees scribed.

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1294, Surveyed May/June 1986 - (DCSO records Vol. 48 Page(s) 18229-30)

The ¼ sec. cor., perpetuated and recorded by Markham in 1951, and further perpetuated and recorded by Byron in 1963, monumented with an iron post, 1½" dia., firmly set, projecting 15" above ground (with an unmarked quartz stone, 11x10x5 ins., alongside), with brass cap mkd. in 1963, from which the remains of the original bearing trees:

A Fir 20" dia., bears S.85°W., 24 lks. dist., with healed blaze. (Record, S.80°W.)

A root crown bears N.80°W., 26 lks. dist., with a Fir, 8" dia., lying alongside, with scribe marks ¼ S visible on a rotted blaze. (Record, 23 lks.)

and bearing trees mkd. by Markham:

A Madrone 20" dia., bears S.44°E., 27 lks. dist., with healed blaze.

A Madrone 22" dia., bears N.71°W., 48½ lks. dist., with illegible bark scribing.

and a new bearing tree:

A Fir 8" dia., bears N.40°W., 42 lks. dist. mkd. ¼ S21 BT.

The corner is located on a SE. slope, 1 ch. N. of a creek, 2 lks. wide, course SW.