

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 400540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6949)

Set a Fir post 4 ft. long, 4" sq., 24" in the ground, for 1/4 sec. cor. marked 1/4 S. on W. face, from which
A Fir 6" dia., bears S.2 1/2°E., 31 1/2 lks. dist. mkd. 1/4 S BT.
A Fir 20" dia., bears N.6°W., 36 1/2 lks. dist. mkd. 1/4 S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Jan. 1963 - C.S. File 52/138-5

Found - Orig. 6" now 20" Fir, S.2 1/2°E., 20.4 ft. We open and find good scribing.
Orig. NW. BT, not found.

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 3 W
1/4 S 9 | S 10
1963

New BTs- 42" R.Fir bears N.49°W., 46.6 ft. scribed 1/4 S9 CSBT
10" Fir bears S.38°E., 58.5 ft. scribed 1/4 S10 CS BT.

Greg Lang - June 1993 - M 123-14

Condition Report

Found - Brass cap.
42" R.Fir stump bears N.49°W., 46.6 ft.
13 1/2" Hemlock bears S.38°E., 58.5 ft. (Record, Fir)
Record Fir stump at S.2 1/2°E., 20.4 ft. is decomposing.

Mark Smalley for Roseburg Resources Feb. 1998 - M 128-45

Found - 1963 County Brass cap on iron pipe.
38" Fir stump, N.49°W., 46.6 ft., healed face
20" Fir stump, S.2 1/2°E., 21.5 ft., (20.4) rotten, orig.
14" Hemlock, S.38°E., 58.5 ft. healed

New Accessories -

12" Fir, S.12°E., 13.4 ft. scribed "1/4S BT"
9" Fir, S.25°W., 22.4 ft. scribed "1/4S BT"
8" Fir, N.10°W., 36.7 ft. scribed "1/4S BT"

Fd. OK, June 1993 by G. Lang - M 123-14