

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol 16 Pages 6945-46)

Set a stone 12 x 10 x 4 ins., 8" in the ground, for ¼ sec. cor., marked ¼ on N. face, from which
A Fir 36" dia., bears N.38 3/4°W., 44 lks. mkd. ¼ S BT.
A Laurel 10" dia., bears S.58°E., 32 lks. mkd. ¼ S BT.

BLM resurvey by Stephen D. Albright and Jack W. Bowder, Cadastral Surveyors, under Group #776, surveyed June/July 1972 - (DCSO records Vol. 36 Page(s) 14980)

Point for the ¼ sec. cor. of secs. 15 and 22, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 30 S R 3 W
1/4 $\frac{S 15}{S 22}$
1972

from which

A Fir 7" dia., bears N.45°E., 72½ lks. mkd. ¼ S15 BT.

A Fir 13" dia., bears S.60¼°W., 94 lks. mkd. ¼ S22 BT.

Corner is located on a spur, sloping S.

Greg Lang - Aug 2005 - C.S. File 65/54-33

Found - Brass cap set by BLM in 1972

21½" fir bears N.44°E., 47.40'

28½" fir bears S.60°W., 62.60'

New - 8½" fir bears S.66½°E., 55.60' scribed "¼ S22 BT"

13½" fir bears N.30½°W., 35.00' scribed "¼ S15 BT"

Note - We set & measured to spikes in the base of all BTs; bearings to the trees are based on BLM's survey of the West line of Section 22.

Corner is located on a spur sloping to the south. There is a road approximately 550 South of the corner. The same road is also about 500' West of the corner.

BLM Corrective Dependent resurvey by A. Bert Skeesick, Cadastral Surveyor, under Group No. 2134, surveyed March/April 2006 - (DCSO records Vol. 56 Page(s) 22104-5)

N.89°40'08"W., bet. secs. 15 and 22 @ 2647.02 ft.

Point erroneously reestablished as the ¼ sec. cor. of secs. 15 and 22, by Albright and Bowder, monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. T30S R3W S15 ¼ S22 1972 from which cont.

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 15 and 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

bearing trees mkd. by Lang, in 2005

A fir, 9" dia., bears S.67°E., 55.5 ft., with scribe marks $\frac{1}{4}$ S22 visible on an unhealed blaze and steel spike, $\frac{1}{4}$ " dia., driven into right side.

A fir, 13" dia., bears N.30 $\frac{1}{4}$ °W., 35.0 ft., with scribe marks $\frac{1}{4}$ S15 BT visible on an unhealed blaze and steel spike, $\frac{1}{4}$ " dia., driven into left side.

This point is not properly positioned and is not utilized in this survey. Remove iron post.

At 2661.55 ft.

Point for the $\frac{1}{4}$ sec. cor. of secs. 15 & 22 at proportionate; there is no remaining evidence of the original cor.

At the cor. point

Set a stainless steel post, 28" long, 2 $\frac{1}{2}$ " dia., 24" in the ground, with brass cap mkd. T30S R3W

$\frac{1}{4}$ $\frac{S\ 15}{S\ 22}$
2006

from which bearing trees mkd. by Albright and Bowder, now re-described relative to the corrected corner

A fir, 22" dia., bears N.54 $\frac{1}{2}$ °E., 58.5 ft., with a healed blaze and steel spike, $\frac{1}{4}$ " dia., driven into left side.

A fir, 27" dia., bears S.52°W., 50.4 ft., with a healed blaze and steel spike, $\frac{1}{4}$ " dia., driven into left side.

Bury a magnet in a white plastic case at the base of the stainless steel post.

Fd. BLM BC and 2 BTs by Corey Woodruff, 9/2014 - M168-61