

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6931)

-----  
Set a Cedar post 4 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S. on W. face, from which  
A Fir 24" dia., bears N.75 1/4°W., 64 lks. dist., mkd. 1/4 S BT  
A Fir 24" dia., bears S.76 1/2°E., 54 lks. dist. mkd. 1/4 S BT.

Survey by Richard L. Templin, Jr. - For: Milo Church School -Nov. 7, 1954 - C.S. File 41/317

-----  
Found - 2" W. stake mkd. R. Thompson, et al.  
Rotted stump of 24" Fir BT with scribing, N.75°15'W., 64 lks.  
30" Fir BT, down and dead, S.76 1/2°E., 54 lks.  
Set 1 1/2" galv. iron pipe with alum. tag mkd. RE 3024.  
Scribed following:  
10" Fir S.38°40'W., 10.2 ft. mkd. 1/4 S34 BT.  
16" Cedar S.79°30'W., 27.5 ft. mkd. N 1/4 S34 BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - March 1963 - C.S. File 52/138-37

-----  
Found - 1 1/2" I.P. and mound of rocks at corner and SW. BT as recorded.  
BT, now 14" Fir, down, bears N.52°E., 16.0 ft. scribed by Templin.  
New BT - 12" Cedar bears S.88°E., 19.2 ft. scribed 1/4 S35 CS BT.

Fd. OK, Aug. 1983 by H. Johnstone - M 95-6

BLM resurvey by Wayne L. Rogers; Lance J. Bishop; James L. White, Cadastral Surveyors, under Group #1133 - Surveyed June 7, 1983/Dec. 12, 1984 - (DCSO records Vol. 47 Page(s) 17853-54)

-----  
The 1/4 sec. cor., perpetuated and recorded by Templin in 1954, and further perpetuated and recorded by Byron in 1963, monumented with an iron pipe 1 1/2" dia., firmly set, projecting 10" above ground, from which the remains of the original bearing trees:

A root hole bears S.76 1/2°E., 54 lks. dist. with down Fir alongside 30" dia., no marks visible.

A Fir stump size indeterminate, bears N.75 1/4°W., 64 lks. dist., no marks visible.

and a bearing tree mkd. by Templin:

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Fir 16" dia., bears S.36½°W., 15 lks. dist. with healed blaze.

and a bearing tree mkd. by Byron:

A Cedar 22" dia., bears S.87 3/4°E., 28 lks. dist. with healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 30 S R 3 W  
1/4  
S 34 | S 35  
1983

Reset iron pipe alongside iron post.