

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6934-35)

Set a stone 13 x 12 x 5 ins., 9" in a mound of stone as it is too rocky to set it in the ground, for 1/4 sec. cor., marked 1/4 on W. face, from which

An Alder 15" dia., bears S.30 1/4°E., 10 1/2 lks. dist. mkd. 1/4 S BT.

A Hemlock 34" dia., bears N.37°W., 52 1/2 lks. dist. mkd. 1/4 S BT.

Survey by Bruce A. Shaner - For: National Plywood Inc. - Wit: Wm. James and W. Griffin - Aug. 16, 1960 - C.S. File 51/105-3

Orig. Stone, now missing, 12"x12"x5", 9" in a mound of stone, with 1/4 on W. face, from which a

34" Hemlock now dead and down, but with the scribes "1/4S" visible on it, bears N.37°W., 52 1/2 lks.

15" Alder now missing, S.30 1/4°E., 10 1/2 lks.

Set a brass rod, 5/8" x 27" in the proper position for the 1/4 corner and from which a:

12" Yew newly scribed "1/4S BT" bears N.28 1/2°W., 27.5 ft.

8" Hemlock newly scribed "1/4S BT" bears N.50°E., 4.0 ft.

D.Fir 72", a line tree as described by the surveyor general, bore South 1.65 chains (108.9 ft.) This tree was logged a year or so ago and only the stump remains, but Wm. James and J.B. Griffin identified the line tree and the corner, prior to the line tree's being cut.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Nov. 1967 - C.S. File 54/52-9

Found - 5/8" Iron rod at 1/4 corner.

12" Yew, now down and burnt, N.28 1/2°W., 27.5 ft., scribe visible "B S".

No trace of NE. bearing tree.

New BTs- 16" Hemlock N.21°W., 34.7 ft. mkd. 1/4 S15 CS BT.

21" Hemlock N.4°E., 55.2 ft. mkd. 1/4 S14 CS BT.

This corner lies approx. 10.0 ft. East of small creek.

Douglas Co. Surveyors Office - L.E. Monrean; R.B. Kimberling, crew - April 26, 1977 - C.S. File 59/31-33

Found - 5/8" Brass rod 18" below ground.

A 16" now 22" Hemlock bears N.21°W., 34.7 ft. Tree has partially healed double blaze, some scribing visible.

(Cont. Next Page)

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A 21" now a 22" Hemlock stump, bears N.4°E., 55.2 ft. Tree blazed and scribed "¼ S14 CS BT"
A 72" Fir stump, orig. line tree, bears S.1½°W., 113.5 ft. (Rec. 108.9 ft.)
Set 1" x 30" I.P. with brass cap attached directly over 5/8" brass rod, cap is stamped Douglas County Surveyor
T 30 S R 3 W
¼ S15 | S14
1977
New BT - A 12" Yewwood bears S.0½°W., 53.7 ft. (to center of tree at BT blaze height). Tree double blazed and scribed "¼ S14 CS BT"

Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. & Roseburg Forest Products - Jan. 2009 - M 158-53

Found - 2½" DC BC dated 1977
32" W.Fir (Rec. Hemlock) bears N.21°W., 34.7' - healed face.
17" badly rotted hemlock bears N.4°E., 55.6' - rotted face.
72" D.Fir stump (orig. line tree) bears S.1½°W., 113.5'
New BTs- 15" D.Fir bears N.45°E., 78.6' - blazed, scribed "¼ S14 BT"

Fd. Ok by R. Quimby, June 2013 - C.S. File 65/78-45

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2813, surveyed Sept 2015/April 2017 - (DCSO records Vol. 58 Page 23501-2)

The ¼ sec. cor. of secs 14 and 15, perpetuated by Shaner, in 1960, from original evidence no longer in existence, further perpetuated by the Douglas County Surveyor's Office in 1967, and by Monrean, Deputy County Surveyor, in 1977, and by Rice, in 2009, monumented with an iron post, 1¼" dia., firmly set, projecting 8" above ground with brass cap **incorrectly** mkd.

DOUGLAS COUNTY SURVEYOR

T 30 S R 3 W

¼ S 13 | S 14

1977

from which the remains of a bearing tree mkd. by Shaner

A burnt, decayed yew stump, size indeterminate, bears N.30°W., 27.5 ft., with a fallen, burnt, decayed yew trunk, size indeterminate, lying alongside, with no marks visible. continued next page

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 500440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

and the remains of the bearing trees mkd. by the Douglas County Surveyor's Office

A decayed hemlock stump, 24" dia., bears N.3¼°E., 55.5 ft., with no marks visible.

A fir, 34" dia., bears N.19¼°W., 34.4 ft., with a healed double blaze.

and the remains of a bearing tree mkd. by Monrean

A root hole bears S.1¾°E., 52.4 ft., with a fallen, decayed yew trunk, 9" dia., lying alongside, with no marks visible on a hollowed blaze.

and a bearing tree mkd. by Rice

A fir, 18" dia., bears N.43¾°E., 78.4 ft., with a healed blaze.

Corner is located on a small island, W., 10 ft. of the main creek channel, 8 ft. wide, course South, and E., 22 ft. of an alternate channel, 4 ft. wide, course S.30°E.

NAD 1983 (2011)

Latitude: 42°58'04.150"N. Longitude: 123°02'28.987"W.