

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Pgs 6887-88)

Set 1/4 sec. post, from which
An Oak 18" dia, bears S.68°E., 66 lks. dit.
An Oak 18" dia., bears N.50°E., 130 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - March 1963 - C.S. File 52/138-33

Found - Orig. 18" now 26" rotted Oak snag, S.68°E., 43.6 ft., shows scribing.
Orig. 18" now 30" down and rotted Oak, N.50°E., 85.8 ft. shows scribing.
Renewed BTs, which show good scribing about 20 years old. We rescribe both Fir bearing trees.

Corner is under butt section of down 36" Fir.
Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W
1/4 S 23
S 26
1963

New BTs- 27" R.Fir bears S.64°E., 48.7 ft scribed 1/4 S26 CS BT
26" R.Fir bears N.56 1/2°E. 66.0 ft scribed 1/4 S23 CS BT

Fd. BC per rec. by Raymond Brown, 2/2007 - M152-60

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2813, surveyed Sept 2015/April 2017 - (DCSO records Vol. 58 Page 23502)

The 1/4 sec. cor. of secs 23 & 26, perpetuated by Byron, Deputy Co Surveyor, in 1963, from original evidence no longer in existence, monumented with an iron post, 1 1/4" dia. firmly set, projecting 4" above ground, with brass cap (properly) mkd.

from which the remains of the bearing trees mkd. by Byron
A fir, 33" dia., bears N.55 3/4°E., 65.2 ft., with a healed double blaze.

A sawed fir stump, 36" dia., bears S.66 1/4°E., 48.6 ft., with a healed double blaze. and a new bearing tree

A fir, 6" dia., bears S.65 3/4°E., 12.3 ft., mkd. 1/4 S26 BT.

Corner is located on a S. slope.
NAD 1983 (2011)

Latitude: 42°56'45.517"N. Longitude: 123°01'53.240"W.

Fd. Ok - James Terrel - 8/2025 - M185-45

continued next page