

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Pages 6933-34)

A Fir 6" dia., which I mark $\frac{1}{4}$ S. on N. side, for $\frac{1}{4}$ sec. cor., from which

A Fir 5" dia., bears S.56 $\frac{3}{4}$ °W., 7 lks. dist. mkd. $\frac{1}{4}$ S BT
A Fir 6" dia., bears N.37 $\frac{1}{2}$ °W., 16 $\frac{1}{2}$ lks. dist. mkd. $\frac{1}{4}$ S BT.

Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Sept. 1967 - C.S. File 54/52-1

Found - Orig. 6" D.Fir now 7", down and burnt, N.37 $\frac{1}{2}$ °W., 10.9 ft., tree had been opened, faint scribe "SB"
Orig. 5" D.Fir now stump flush with ground, S.66 $\frac{3}{4}$ °W., 4.6 ft.

6" now 8" Corner Tree with rotted face, tried to get a ring count but tree grew too slow to count.
Calls from ravines hit pretty good on top of ridge.

Set Brass cap at $\frac{1}{4}$ cor. mkd: County Surveyors Office
T 30 S R 3 W
 $\frac{1}{4}$ S 14
S 23
1967

New Bearing Objects:

RR Spike in top of 42" stump, S.75°W., 31.5 ft.
RR Spike in top of 28" stump, N.4°W., 29.4 ft.

This corner lies on top of small ridge running about N-S.

Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. & Roseburg Forest Products - Jan. 2009 - M 158-53

Found - 2 $\frac{1}{2}$ " DC BC dated 1967
RR Spike in top of 42" D.Fir stump bears S.75°W., 31.5'
RR spike in top of 28" D.Fir stump bears N.4°W., 29.4'

New BTs- 10" P.Pine bears N.23°E., 24.2' - blazed, scribed " $\frac{1}{4}$ S14 BT"
10" P.Pine bears S.39°E., 14.3' - blazed, scribed " $\frac{1}{4}$ S23 BT"

continued next page

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2813, surveyed Sept 2015/April 2017 - (DCSO records Vol. 58 Page 235499-23500)

The ¼ sec. cor of secs 14 & 23, perpetuated by the Douglas Co Surveyor's Office in 1967, from original evidence no longer in existence, further perpetuated by Rice, in 2009, monumented with an iron post, 1¼" dia., firmly set, projecting 13" above ground, with brass cap (properly) mkd from which accessories by the Douglas Co. Surveyor's Office

A railroad spike driven into the top of a fir stump, 42" dia., bears S.75½°W., 31.6 ft., with no marks visible.

A railroad spike driven into the top of a fir stump, 28" dia., bears N.3¾°W., 28.8 ft., with no marks visible. and bearing trees mkd. by Rice

A pine, 12" dia., bears N.23°E., 24.2 ft., with a healed blaze.

A pine, 11" dia., bears S.38¾°E., 14.2 ft., with a healed blaze.

Corner is located on a SE. slope.