

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #73, dated June 8, 1857 - (DCSO records Vol. 16 Page(s) 6888)

Set post cor. secs. 13, 14, 23 and 24, from which

- A Fir 24" dia., bears S.16°W., 20 lks. dist.
- A Fir 15" dia., bears S.5°E., 35 lks. dist.
- A Fir 36" dia., bears N.80°W., 42 lks. dist.
- A Fir 24" dia., bears N.85°E., 30 lks. dist.

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Page(s) 6923)

The cor. to secs. 13, 14, 23 and 24 is gone. I find the 4 original witness trees at cor. point. I set a Cedar post 4 ft. long, 4" sq., 24" in the ground, mkd. T30S S13 on NE.; R3W S24 on SE.; S23 on SW.; and S14 on NW. faces, 1 notch on E. and 3 notches on S. edges, from which

- A Fir 24" dia., bears N.85°E., 30 lks. dist. mkd. T30S R3W S13 BT.
- A Fir 15" dia., bears S.5°E., 35 lks. dist. mkd. T30S R3W S23 BT.
- A Fir 24" dia., bears S.16°W., 20 lks. dist. mkd. T30S R3W S24 BT.
- A Fir 36" dia., bears N.80°W., 42 lks. dist. mkd. T30S R3W S14 BT. This tree is marked in the bark, I mark in the wood "T30S R3W S14 BT"

Douglas Co. Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell, crew - March 1962 - C.S. 49/47-27

Found - Orig. 24" now 32" Fir stump, S.16°W., 13.2 ft., shows scar.

- Orig. 15" now 16" Fir snag, S.5°E., 23.1 ft., shows good scribing.
- Orig. 36" now 40" Fir stump, N.80°W., 27.7 ft. shows scar.
- Orig. 24" now 30" Fir stump, N.85°E., 19.8 ft., shows scar.

Set Brass cap at cor. mkd: County Surveyors Office

T 30 S R 3 W
S 14 S 13
S 23 S 24
1962

New BTs- 8" Cedar bears N.24°W. 29.0 ft. scribed S14 T30S R3W
 24" Cedar bears S.59½°W., 35.3 ft. scribed S23 T30S R3W CS BT.
 8" Fir bears S.38°E., 8.4 ft. scribed S24 CS BT.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

26" R.Fir bears N.85°E., 58.3 ft. scribed S13 T30S R3W CS BT.
Douglas Co. Surveyors Office - John M. Powell, Frank Jones & Joe Brady, crew - Nov. 1967 - C.S. File 54/52-4 ----- Found - DCS0 brass cap at sec. corner. 8" Cedar now badly burnt, N.24°W., 29.0 ft. 24" Cedar S.59½°W., 35.3 ft., scribe visible "T30S R3W S22 CS BT". 8" W.Fir now 10", S.38°E., 8.4 ft., shows good scars. 26" D.Fir N.85°E., 58.3 ft. shows scribing. New BT - 13" Maple N.22½°W., 59.6 ft. mkd. T30S R3W S14 CS BT This corner lies on N-S slope approx. 600 ft. West of road.
Tony Hostetter - For: Seneca Jones Timber Co. - April 2003 - M141-79 ----- Found - 1962 brass cap as described by Powell in 1967 C.S. File 54/52, from which: 32" fir, 1962 BT, possible face but no tag, bears N.83°42'E., 58.3 ft. (placed spike in root collar which is N.82°42'E., 56.0 ft. from brass cap. Tagged) New BTs- 10" fir scribed "S13 SW BT" bears N.30°E., 14.4 ft. to spike. 14" fir scribed "S24 SW BT" bears S.78°00'E., 79.2 ft. to spike. 14" fir scribed "S14 SW BT" bears N.87°W., 9.8 ft. to spike.
Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. & Roseburg Forest Products - Jan. 2009 - M 158-53 ----- Found - 2½" DC BC dated 1962 32" D.Fir stump bears S.16°W., 13.2' - scribing visible on opened face. 40" D.Fir stump bears N.80°W., 27.7' - healed face. 30" D.Fir stump bears N.85°E., 19.8' - rotted face. 24" rotted cedar stump bears S.59½°W., 35.3' - rotted face. 26" Maple bears N.22½°W., 59.6' - burled face. 30" D.Fir bears N.84°E., 58.3' (56.0' to spike in bole) - healed face. 11" D.Fir bars N.30°E., 15.1' (14.4' to spike in bole) - healed face. continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

15" D.Fir bears S.78°E., 80.0' (79.2' to spike in bole) - scribing visible.
15" D.Fir bears N.87°W., 10.6' (9.8' to spike in bole) - scribing visible.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2813, surveyed Sept 2015/April 2017 - (DCSO records Vol. 58 Page 23498-9)

The cor. of secs. 13, 14, 23, and 24, perpetuated by Byron, in 1962, further perpetuated by the Douglas County Surveyor's Office in 1967, and by Hostetter, in 2003, monumented with an iron post, 1¼" dia., firmly set, projecting 14" above ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees

- A fir stump, 30" dia., bears N.85°E., 19.8 ft., with a healed blaze.
- A fir stump, 16" dia., bears S.5°E., 23.1 ft., with illegible scribe marks visible on a partially opened blaze.
- A fir stump, 25" dia., bears S.16°W., 13.2 ft., with illegible scribe marks visible on a partially opened blaze.
- A fir stump, 42" dia., bears N.80°W., 27.7 ft., with a healed blaze.

and the remaining bearing tree mkd. by Byron

- A fir, 31" dia., bears N.83¼°E., 57.7 ft., with a healed blaze.

and the BT mkd. by the Douglas Co. Surveyor's Office in 1967

- A maple, 22" dia., bears N.22°W., 58.2 ft., with a healed blaze.

and the bearing trees mkd. by Hostetter

- A fir, 12" dia., bears N.28°E., 16.1 ft., with a healed blaze.
- A fir, 16" dia., bears S.87½°E., 80.2 ft., with a healed blaze.
- A fir, 15" dia., bears N.83¼°W., 10.2 ft., with a healed blaze.

Corner is located on a NE. slope.