

PRIMARY CORNER DESCRIPTION SE Cor. Sec. 36, T29-3 (on N. bdy. S. 1)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 15 Page(s) 6320)

Section cor. Set post for cor. to secs. 36, 31, 1, 6, and Tps. 29, 30 S., R's. 2 nd 3 W., from which
A Fir tree 12" dia., bears N.43°E., 51 lks.
A Fir 14" dia., bears S.56°E., 45 lks.
A Fir 16" dia., bears S.52°W., 37 lks.
A Fir 10" dia., bears N.45°W., 4 lks.

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 16 Pgs 6918-19)

Byar's corner, which is a Fir tree 16" dia., and not a post as stated in the field notes furnished me, marked T29S S31 on NE.; R2W S6 on SE.; T30S S1 on SW.; and R3W S36 on NW. faces with 6 notches facing each cardinal point, from which
A Fir 12" dia., bears N.43°E., 51 lks. dist. mkd. T29S R2W S31 BT.
A Fir 14" dia., bears S.56°E., 45 lks. dist. mkd. T30S R2W S6 BT.
A Fir 16" dia., bears S.52°W., 37 lks. dist. mkd. T30S R3W S1 BT.
A Fir 10" dia., bears N.45°W., 4 lks. dist. mkd. T29S R3W S36 BT.
As this is not a cor. to T30S Rs. 2 and 3 W., I destroyed the marks on the SE. and SW. faces of this tree cor. and also the marks on the 2 Fir witness trees S. of cor. in T30S R3W.

GLO survey by Fred Mensch, U.S. Deputy Surveyor - under Contract #782, dated Dec. 1, 1908 - (DCSO records Vol. 16 Page(s) 6788)

(Page 6788)
The old cor. of Tp. 29 S, Rs. 2 and 3 W., which is a Fir 20" dia., with marks defaced, witnessed as described by the surveyor general. This cor. will be re-established as the SE. cor. of T29S R3W.
(Page 6789)
The original cor., a Fir 20" dia., for cor. of Tps 29 S, R3W and 30 S, R2W, I re-mark T30S R2W S6 on NE.; and T29S R3W S36 on NW.; side with 6 notches on N. and W. sides, from which
A Fir 18" dia., bears N.55½°E., 91 lks. dist. mkd. T30S R2W S6 BT.
A Fir 15" dia., bears N.45°W., 4 lks. dist. mkd. T29S R3W S36 BT.
I obliterate marks on former brg. tree referring to T29S R2W.

TOWNSHIP 30 RANGE 03 POINT IDENTIFIER # 677700

PRIMARY CORNER DESCRIPTION SE cor S 36, T29-3 (on N bdy S 1)

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. Stoffel, crew - Dec. 1962 - C.S. File 52/126-90

Found both original BTs and corner tree, all as recorded. Orig. 15" now 20" Fir, N.45°W., 2.6 ft., shows good scar, face may be rotted. I rescribe this BT "S36 T29S R3W CS BT".

BLM resurvey by Peter Peterson and Daniel Berry under Group #749, surveyed July/Aug. 1971 (DCSO records Vol. 36 Page(s) 14916-17)

The SE. cor. of T29S R3W, monumented by a Fir 23" dia., with scribe marks T30S R3W visible on opened blaze on SW. face and healed blaze on NE., SE., and NW., faces, from which the original bearing trees

A Fir 30" dia., bears N.55½°E., 91 lks. dist., with healed blaze. (Mensch record)

A broken Fir stump 33" dia., bears S.56°E., 45 lks. dist., with healed blaze. (Bushey record) Bushey and Mensch both report destroyed marks on this tree.

A Fir 35" dia., bears S.52°W., 37 lks. dist., with healed blaze. (Bushey record) Bushey and Mensch both report destroying marks on this tree.

A Fir 20" dia., bears N.45°W., 4 lks. dist. with healed blaze. (Bushey record)

and a new reference monument

An Iron post 28" long, 2½" dia., set 22" in the ground, for a reference monument, bears N.56°W., 30 lks. dist., with brass cap mkd. T29S R3W S36 RM 1971 and an arrow pointing to the corner.

Fd. OK, Nov. 1984 by H. Johnstone - M 97-65

David Edwards - For: Roseburg Resources - Oct. 2016 - M172-56

Found - 25" dia. Fir corner tree stump.

1971 BLM brass cap ref. mon. bears N.56°W., 19.8'

A 16" dia. Fir snag with H.B. bears N.45°W., 2.6'

A 34 dia. Fir stump, with H.B. bears N.55½°E, 57.9'

New BT - A 9" dia. Fir scribed "T29S R3W S36 BT" bears N.26°W., 6.1 feet

A six foot steel post is set 2 feet west