

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 039060

PRIMARY CORNER DESCRIPTION Pt on SF Bdy Beckworth DLC #39

Alias 041010 Description NE Cor Boyle DLC #41  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey) (Pg. 597 and 601 DLC Volume)  
-----  
(Page 597)  
Set a post marked from which  
A B.Oak, 20" dia., bears N.15°W., 80 lks.  
(Page 601)  
Set a post marked a quadrangular trench & stone in the center

Resurvey - Wm. Thiel, under Contract dated Feb. 5, 1889 (DLC Volume, page 694 & 699)  
-----  
The post for this corner is gone, but the stump of a B.Oak corresponding in size, and direction & bearing with the field notes of orig. survey, stands, but the marks are entirely obliterated. I restore this corner by setting a basalt stone 10x8x8", 7" in the ground, marked 39 on NW face (pg. 699, marked 41 on SW face), raised a mound of stone alongside.

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20134)  
-----  
Point for the NE. cor. of DLC 41, at proportionate dist., determined by the Grant Boundary Method between the reestablished SW. cor. of DLC 42 and the reestablished NE. cor. of DLC 42, there is no remaining evidence of the original corner.  
Set a stainless steel post, 28" long, 2½" diam., 28" in the ground, with brass cap mkd.  

T30S	R4W
S 8	C 42
C 41	
	1994

  
from which  
A maple, 12" diam., bears N.15¼°E., 28 lks., mkd. X BT.  
An ash, 14" diam., bears N.21 3/4°W., 49 lks., mkd. S8 BT.  
Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Mike Koch - 2/28/2017 (filed 11/7/2022) - C.S. File 67/54-53  
-----  
Found - 1993-1995 BLM resurvey a 3¼" brass cap on a 2½" O.D. I.P. sitting plumb with top of brass cap flush with road fill bank surface. (BC properly mkd)  
continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 039060

PRIMARY CORNER DESCRIPTION Pt. on SE Bdy Beckworth DIC #39

Alias 041010 Description NE Cor. Boyle DIC #41

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description \_\_\_\_\_

No evidence of earlier monuments is found.  
No evidence remains of the 1855 & 1889 BTs  
A Maple 12" now an 18" dia., Maple with a fully healed blaze; bears N.15 $\frac{3}{4}$ °E., 18.5 ft. (as per rec.) 1994 BLM  
An Ash 14", now a 17" Ash with a fully (healed) double blaze; bears N.21 $\frac{3}{4}$ °W., 32.3 ft. (as per rec) 1994 BLM  
New - A 1/2" dia., iron rod with a broken plastic cap mkd "FED HW CP P  $\Delta$  314" bears S.24 $\frac{3}{4}$ °W., 50.95 ft. (This ref. is 1.2 south'ly from south edge of hwy AC and buried 1 ft. deep in the rd shoulder.  
A  $\frac{5}{8}$ " dia., iron rod with a 1 $\frac{1}{2}$ " alum cap mkd "OREGON STATE HWY DEPT" bears S.38 $\frac{3}{4}$ °W., 2.83 ft. (this ref. is flush with surface in road fill bank)  
Note - Sketch shows NE cor. of Hay barn bears S.18°W., 85'  
The BC/IP corner monument is in the north side fill slope of the Tiller Trail Hwy which is also the south or left bank of the South Umpqua River.