

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 039120

PRIMARY CORNER DESCRIPTION Pt on SE Bdy Beckworth DLC #39

Alias 043010 Description NE Cor Andrew Chapman DLC #43
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey) Page 598 and 605, DLC Volume)

(Page 598) Set a post marked, from which
A B.Oak 12" dia., bears N.10°W., 161 lks.

(Page 605)
Set a post marked a quadrangular trench and stone in the center.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records DLC Volume Page 703)

At the NE. Cor., the old post is gone, but the stump of a B.Oak on Claim No. 39, and corresponding in size and direction with the description in field notes of survey of Claim 39 (being the same corner) furnished me, is still standing. I restore this cor. by setting a basalt stone 12 x 8 x 8 ins., 8" in the ground mkd 43 on SW. face, from which
A B.Oak 36" dia., bears N.77 3/4°W., 196 lks. dist. mkd.
T30S R4W W.C. 39 BT.

Douglas Co. Surveyors Office - Ben B. Irving - Wit: N.E. Richardson and R.L. Irving - Feb. 26, 1940 - C.S. File 16/55

Location identified by a rock with X chiseled on the top. While I was on the ground, a State Highway Dept. grader cut the top off of this rock, which is located in the edge of the road. Underneath this rock was another rock marked with an X with top dimensions of 8" x 10". A bottle was buried alongside. The rock which was on top was turned over and placed with its top flush with ground and marked with cross. This rock is 8x10x18".

A Maple 24" dia., bears S.2°45'W., 86.0 ft.
An Oak 54" dia., bears N.83°35'W., 161.0 ft.
A Fir 20" dia., bears N.55°15'E., 126.2 ft.
All blazed and scribed "N.E. D.L.C 43 C.S. B.T."

Douglas Co. Surveyors Office - James W. Byron - Dale McFarland & John Powell, crew - Feb. 1962 - C.S. 49/67-37

Found - 1/2" I.R. at corner and at edge of black top, 1" under surface. Fir BT shows good bark scribing. Maple BT shows good scar. Both check record. Oak BT, not found.

USBM mkd. U499 bears S.60°W., 33.8 ft.
1949

continued next page

PRIMARY CORNER DESCRIPTION Pt. on SE Bdy Beckworth DLC #39

Alias 043010 Description NE Cor. Andrew Chapman DLC #43
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20133)

The NE. cor. of DLC 43, on the W. bdy. of DLC 44, perpetuated by Irving, in 1940, further perpetuated by Byron, in 1962, and is accepted as a careful and faithful determination of the original corner based on use; monumented with an iron rod, 1/2" diam., firmly set 4" below ground, from which the remains of bearing trees mkd. by Irving:

A fir snag, 32" diam., bears N.54 1/2°E., 192 lks., with fragmentary scribe marks visible on the bark.

A maple, 81" diam., bears S.2 1/4°W., 132 lks., with healed blaze.

At the corner point

Set a stainless steel post, 28" long, 2 1/2" diam., 33" in the ground directly over the iron rod, with brass cap mkd.

T30S	R4W
S 8	C 44
C 43	
	1994

and a new bearing tree

A maple, 16" diam., bears N.54°E., 182 lks., mkd. X BT. Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

The corner is located South, 0.25 chs. dist. from the center of County Road No. 1 (Tiller Trail Highway), asphalt-surfaced, 45 lks. wide, bears N. 85° E. and S. 80° W.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 9/14/2005 - C.S. File 67/13-8

Found - 3" brass cap, markings are illegible. Lies slightly under edge of road 8" below surface of asphalt, 13 ft. from centerline.

16" Maple now 17" measured at 2 ft. above ground (split trunk) high & low fully healed blazes visible on most westerly trunk.

Fir snag now tipped out stump (rec. N.55 1/4°E., 126.2 ft.) 1940 BT

81" Maple now 90" no markings evident. Tree is now multi trunked & split down the middle & is to be removed in future.

3 1/2" brass disc. set in concrete "US COAST & GEODETIC SURVEY BENCHMARK U499 1949" bears S.60°W., 33.8 ft. (agrees with record)

continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 039120

PRIMARY CORNER DESCRIPTION Pt. on SE Bdy Beckworth DLC #39

Alias 043010 Description NE Cor. Andrew Chapman DLC #43
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New - 38" D.Fir, double blazed scribed "DLC 39 CS BT"
bears N.74°W., 134.9 ft.
Note - Compass decl. 16¾°E.

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - Dec. 12, 2018 - C.S. File 67/49-3

Found - A 2½" O.D. stainless steel post by B. Seibold, firmly set, buried 8" below the ground with a ¾" diam. brass cap (properly) marked

BTs by Irving in 1940 -

A 91" diam. maple bears S.01°W., 87.1 ft. with a healed blaze. (rec. S.2¼°W.)

A 32" D.Fir stump bears (rec. N.54½°E., 126.7 ft.) tipped out of position with no clear position to measure

BT by Seibold in 1995 -

A 19" diam. maple bears N.54°E., 120.5 ft. with a healed blaze. (rec. 182 lks.)

Accessories by flause, DCS0, in 2005 -

A ¾" diam. brass disc set in concrete, USC&GS benchmark "U 499 1949" bears S.57°22'W., 33.65 ft (rec. S.60°W., 33.8 ft.)

A 43" diam. D.Fir bears N.75¾°W., 134.9 ft with a healed blaze (rec. N.74°E.)

Note - Basis of bearings: 1998 USBLM dependent resurvey. S.71°21'33" W. as the computed inverse between the NE corner of DLC 43 & the NE corner of DLC 42 The corner falls 13 ft. south of the centerline of South Umpqua Co. Rd. No. 1 (OR 227) and just South of and 8" below the edge of pavement.

All BTs have BT tags attached. All new BTs have double blazed faces with bearing measured to the center of the trees at the root crown and distances measured to a 4" mag hub in the side and center of the root crown.

Compass declination: 14¾°E.