

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 047060

PRIMARY CORNER DESCRIPTION SE Cor. George T. Day DLC #47

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - GLO survey by Bowman and Burnett, under Contract dated Sept. 1855 (DLC survey Volume Page 611)

-----  
Set a post marked a quadrangular trench and stone in the center.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records DLC Volume Page 712)

-----  
The old post is gone, and cultivation has obliterated all traces on the ground; I proved this cor. by going to the ¼ sec. cor. bet. secs. 10 and 15 and running West 1673 lks. and South 6.34 chs. to this corner. I restore this cor. by setting a Cedar post 4½ ft. long, 4" sq., 24" in the ground marked T30S R4W C.47 on NW. face, from which  
An Alder 12" dia., bears N.75¼°E., 410 lks. dist. mkd. T30S R4W C.47 BT.

G.G. Stewart, Deputy Co. Surveyor - Wit: Montgomery, Morgan, Moore, Beals - Dec. 29, 1922 - M 2-9; Vol. 3 Pg. 136 and C.S. File 7/31

-----  
Reestablished by running from West cor. to West and SW. corner of Claim 48 to North, according to distances from resurvey of Claim 47. Set Iron wagon axle for corner at edge of county road. Marked:  
A 14" W.Oak S.73°E., 223.9 ft.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey and Mike Darby, crew - Aug/Sept. 1963 - C.S. File 53/26-106

-----  
Found - 14" now 20" W.Oak S.73°E., 223.9 ft. open and find good scribing.  
Do not find I.bar at corner.  
Corner falls on highway road asphalt surface. Metal finder does not operate properly on road surface in this area. We measure distance from SW. corner DLC #48, 1259.3 ft. which is as shown by Stewart's 1922 survey, checks OK.  
Set ¾" I.R. flush at corner 6 ft. West of centerline.  
New BTs -20" R.Fir bears S.74°E., 193.3 ft. scribed SE DLC 47 CS BT.  
Rescribe-20" W.Oak S.73°E., 223.9 ft. SE DLC 47 CS BT.

Fd. BTs Sept. 1984 by Wm. Ruppert - C.S. File 58/215

(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 047060

PRIMARY CORNER DESCRIPTION SE Cor. Geo. T. Day DLC #47

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas Co. Surveyors Office - Randall Smith and Stephen  
Flause, crew - March 8, 1990 - C.S. File 64/6-7

-----  
Found - No corner monument found. Corner lies near center  
line of highway. An attempt was made to locate  
previously set monuments with a metal detector,  
had metal reading all over road, not able to  
locate monuments.

14" now 23" dia. W.Oak with a fully healed double  
blaze bears S.73°E., 223.9 ft. (agrees w/rec.)

20" now 26" dia. D.Fir with a fully healed double  
blaze bears S.74°E., 193.3 ft. (agrees w/rec)

Set 1 1/8" dia. head on an 8" long boat spike set flush in  
asphalt at a point determined from bearing trees.

New Accessories:

16" dia. Apple tree bark scribed "SE DLC 47 CS BT"  
bears S.52¼°E., 155.2 ft.

SE. concrete foundation corner of garage bears  
N.66°W., 102.5 ft.

1/2" Iron pipe protruding 7" from center of a 30" x  
35" x 6" deep concrete high post slab, I.P. bears  
N.13½°E., 189.4 ft.

Corner lies approx. 3 ft. West of centerline of highway at  
South end of Days Creek community.