

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6992)

Set ¼ sec. post at average distance, from which
A B.Oak 18" dia., bears N.77°W., 130 lks. dist.
A W.Oak 18" dia., bears S.13°E., 210 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7084)

The post set for this corner is gone, fire having been through here, probably 20 years ago. The bearing tree in Sec. 19, a B.Oak is lying down, showing axe marks, but no letter distinctly, simply surveyor marks. Nothing remains of the W.Oak in Sec. 30. I restore this corner by setting a basalt rock 15x8x7 ins., 10" in the ground, marked ¼ on N. face, from which
A Laurel 6" dia., bears South, 7 lks. dist., mkd. ¼ S BT
A Fir 12" dia., bears N.80°E., 17 lks. dist. mkd. ¼ S BT

Ben B. Irving, Deputy Co. Surveyor - Wit: Herbert Beyers; Mc. Huntington - Jan. 27, 1930 - C.S. File 5/54 (and "old" corner book, Page 201)

Location identified from one original BT, as described in govt. field notes, 12" now 24" Fir, N.80°E., 17 lks. A 6" Laurel, South, 7 lks., down and rotting. Black rock knocked out and in creek. Reset rock, chisling ¼ on South face.
Blaze and scribe:
18" Fir N.45°E., 70 lks. ¼ S19 CS BT.
26" Fir S.45°W., 67 lks. ¼ S30 CS BT.

Survey by John H. Markham, Jr. - Wit: B.E. Blomgren - For: Stomar Lumber Co. - June 9-10, 1953 - C.S. File 41/161-5

Determined by Orig. BTs.
24" Fir bears N.80°E., 11.0 ft.
30" Fir stump bears S.45°W., 44 ft.
30" Fir bears S.45°E., 46 ft.
At corner point, Set 1" x 30" Iron pipe, from which
A Maple 13" dia., bears S.2°W., 13½ ft. mkd. ¼S 2880 BT.
There is a fence running N. and W. from corner.
Sec. line bears S.82°W.
Sec. line bears S.87°30'E. (Var. 20°00')

(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 140300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 19 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - July 1963 - C.S. File 53/26-79

Found - 1" I.P. in mound of stone at corner.
 Stumps of all BTs cut low. No scribing found.
 Orig. NE. BT, now burned snag, shows burned face.
New BTs - 6" Maple bears S.25°W., 64.7 ft. scribed ¼ S30 CS BT
 12" Fir bears N.22°W., 69.8 ft. scribed ¼ S19 CS BT.
Cor. bears S.80°W., 11.0 ft. from fence corner - fences
running W. and N.

Survey by Mark Smalley - For: Roseburg Resources - May 20, 1991 - M 113-18

Found - 1" Iron pipe set by Markham in 1953.
 12" Fir bears N.22°W., 69.8 ft. Snag.
 8" Maple bears S.25°W., 64.7 ft., healed face.
New BT - 14" Cedar bears S.71°E., 58.3 ft. scribed S ¼ S19
 BT.