

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7007)

-----  
Set ¼ sec. post, at proper dist., from which  
A Laurel 20" dia., bears N.75°W., 24 lks. dist.  
A B.Oak 6" dia., bears N.60°E., 57 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7096)

-----  
The post for this corner is gone, but both bearing trees are standing. I restore this corner by setting a Fir post, 3 ft. long, 3" sq., 24" in the ground, marked ¼ S on W. face, from which

A Laurel 36" dia., bears N.75°W., 24 lks. dist. mkd. ¼ S BT.

A B.Oak 12" dia., bears N.45°E., 97 lks. dist. mkd. ¼ S BT.

These are the old bearing trees, whose marks being overgrown and dim, I renew.

George J. Wenderoth, Deputy Co. Surveyor - Wit: Frank Loso; Lawrence Michaels - May 23, 1949 - (No record source found)

-----  
Found both BTs in good shape:  
36" Laurel N.75°W., 15.8 ft.  
12" B.Oak N.45°E., 64.0 ft.  
Drive 1" Iron pipe for corner.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - Aug. 1963 - C.S. File 53/26-54

-----  
Found - 1" I.Pipe at corner.  
Orig. 36" now 42" Laurel N.65°E., (Not N.75°W.) 15.8 ft.  
38" B.Oak N.25°E., 66.0 ft., not N.45°W., 64.0 ft.  
Fence corner bears N.85°E., 38.0 ft. from I.P. - fences running South and East.  
New BTs -9" R.Fir N.19°E., 27.8 ft. scribed ¼ S5 CS BT.  
Rescribe orig., now 42" Laurel N.65°W., 17.0 ft. "¼ S6 CS BT"

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20122-3)

-----  
From the 1/4 sec. cor. of secs. 5 & 6, perpetuated by Byron, in 1963; monumented with an iron pipe, 1 1/4" diam., firmly set, projecting 8" above ground, from which an original bearing tree:

A madrone, 45" diam., bears N.65°W., 24 lks., with scribe marks S6 CS B visible on partially decayed, open blaze. (Record, N.75°W.)

and the remains of a bearing tree mkd. by Byron

A fir snag, 12" diam., bears N.17 1/4°E., 43 lks., with healed double blaze.

At the corner point

Set a stainless steel post, 28" long, 2 1/2" diam., 26" in the ground, directly over the iron pipe, with brass cap mkd.

T30S R4W  
1/4  
S 6 | S 5  
1994

from which a new bearing tree

A fir, 11" diam., bears N.39 3/4°E., 61 lks. mkd. 1/4 S5 BT. Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

The corner is located at a fence corner, with woven wire fences extending S. and E.

Ronald Quimby - For: James Little - April 1999 - M 129-44

Found - BLM brass cap mkd:

T30S R4W  
1/4  
S 6 | S 5  
1994

A 46" Madrona bears N.65°E., 15.8 ft., partially opened face.

A 12" Fir (down) N.17 1/4°E., 28.4 ft., healed face.

A Fir N.39 3/4°E., 40.3 ft., healed face.

Note - BTs are from a 1994 BLM resurvey that has not been filed as of the date of this survey.