

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 240200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 17 Page(s) 7122)

Set a stone 12x10x8 ins., 8" in the ground for ¼ se. cor., marked ¼ on N. face, from which
A Fir 12" dia., bears N.41°E., 42 lks. dist. mkd. ¼ S BT.
A Fir 11" dia., bears S.37 ¾°W., 59 lks. dist. mkd. ¼ S BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - July 1963 - C.S. File 53/26-72

Found - Stone at corner and orig. BTs as recorded.
Orig. 11" now 18" R.Fir S.38°W., 27.7 ft. We open and find old axed face.
NE. BT, now snag, shows scar.
Set brass cap alongside corner stone and marked:
County Surveyors Office
T 30 S R 4 W
¼ S 29
S 32
1963
New BT - 10" R.Fir bears N.22°E., 52.3 ft. scribed ¼ S29 CS BT.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2872, surveyed April 2017/Oct. 2019- (DCSO records Vol. 59 Page 23847)

The ¼ sec. cor. of secs. 29 & 32, perpetuated by Byron in 1963, monumented with an iron post, 1¼" dia., firmly set, with top 24" below the surface of the ground, with a brass cap (properly) mkd.
from which the remains of the original BTs
A burnt decayed fir stump, size indeterminate, bears N.41°E., 27.7 ft., with a healed blaze.
A fir, 23" dia., bears S.37¾°W., 38.9 ft., with a healed blaze.
and a BT mkd. by Byron
A fir, 22" dia., bears N.20¾°E., 52.4 ft., with a healed double blaze.
Corner is located in the east berm of an old skid trail, 10 ft. wide, bears N. and S. 10° W. Dug the berm out so the iron pipe is now flush with the surface of the ground