

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7007)

Set ¼ sec. post, at average dist., from which
A B.Oak 20" dia., bears S.18°W., 40 lks. dist.
A B.Oak, 18" dia., bears N.18°W., 68 lks. dist.

GL0 survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7094)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N. face, from which
A Laurel 4" dia., bears N.38 ¾°E., (?) lks. dist. mkd. ¼ S BT. (A letter dated April 1960 filed in C.S. File 51/85, supplied the missing distance) 25 lks.
A Laurel 6" dia., bears S.6½°W., 19 lks. dist. mkd. ¼ S BT.

The old post, nor the old bearing trees could not be found. This is a locality which has been burned over, but I think there is some mistake in the field notes, as there are no oak trees growing here.

Survey by John H. Markham, Jr. - Wit: Geo. Vaughn - July 1951 - C.S. File 40/179-5

Report only.
A Laurel 7" dia., bears N.39°E., 18.0 ft. dist. chopped out, scribe showing. Could not find other tree. Corner lies 50 ft. North of side ridge on North slope. I blazed a line West from corner for a 1/4 mile.

Survey by John H. Markham, Jr. - Wit: R.G. Boyd - For: Stomar Lumber Co. - May 1, 1958 - C.S. File 42/356-1

Determined by O.B.T.s:
Laurel stump hole bears S.6½°W., 12.0 ft. dist.
12" B.Oak snag, live, bears N.39°E., 18.0 ft. dist. O.B.T.
At Corner point, found 3" x 3" scribed wood post and Set a steel fence post, from which
9" Fir bears N.35°E., 9.2 ft. mkd. ¼ S5 BT.
16" Laurel bears S.30°E., 14.8 ft. mkd. ¼ S8 BT.
4" Fir bears S.49°W., 18.0 ft. mkd. ¼ S8 BT.
7" Fir bears S.80°W., 20.0 ft. mkd. ¼ S8 BT.

(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 5 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

(Note: a notation of the above Markham visit recorded in the former renewal records, Ren. #134, states: " No scribing, not orig. BT. I do not believe this to be the true cor.") - J.W.B. July 14, 1963 - Byron's record probably filed with his notes from that period, C.S. File 53/26-87 - V.Laugen, Apr. 1996

Fd. Ok by Harold Ball Nov. 1975 - M 58-47

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCS0 records Vol. 52 Page(s) 20142-3)

The ¼ sec. cor. of secs. 5 & 8, perpetuated by Markham, in 1958, from original evidence no longer in existence, further perpetuated by Ball, in 1975; monumented with a steel fence post, firmly set, projecting 4" above ground, from which the remains of bearing trees mkd. by Markham:

A root hole, bears N.38°E., 12 lks., with decayed fir trunk, size indeterminate, alongside, no marks visible.

A sawed madrone stump, 19" diam., bears S.30°E., 22½ lks. dist., with scribe marks BT visible on open blaze.

At the corner point
Set a stainless steel post, 28" long, 2½" diam., 24" in the ground, with brass cap mkd.

T30S R4W
¼ $\frac{S \ 5}{S \ 8}$
1994

and new bearing trees

A cedar, 14" diam., bears S.7°W., 120 lks., mkd. ¼ S8 BT.

A cedar, 18" diam. bears N.72¼°W., 101 lks., mkd. ¼ S5 BT.

Deposit a white "DEEP-1" magnetic marker at base of and steel fence post alongside of stainless steel post.

The corner is located at a fence corner, with woven wire fences extending N. and E.