

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7069)

-----  
Set a Fir post 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor. mkd. 1/4 S on the W. face, from which  
A Fir 36" dia., bears N.85°E., 16 lks. dist. mkd. 1/4 S BT.  
A Fir 24" dia., bears S.84°W., 53 lks. dist. mkd. 1/4 S BT.

Cor. Fd. and used in GLO survey by Wm. M. Bushey, under Contract #620, dated June 17, 1893 - (DCSO Records, Vol. 17 Pages 7115-16)

Survey by John H. Markham, Jr. - April 5, 1949 - C.S. File 40/179-1

-----  
Determined from the remains of O.B.T.:  
Burnt stump bears N.85°E., 16 lks.  
Fir tree bears S.84°W., 53 lks., this BT in good condition.  
Set 3" Fir post for corner, from which  
Fir 18" dia., bears S.10°W., 38 ft., bark scribed "1/4 S 2880 BT".  
This 1/4 cor. is 763 ft. South of the Beals Creek Road. The sec. line is fenced North. The centerline is fenced East and West from this corner.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - June 1963 - C.S. File 53/26-66

-----  
Found - Post and 3/4" I.Pipe at corner. (Pipe not recorded)  
34" Fir S.84°W., 35.0 ft. dead, good scar.  
18" Fir S.10°W., 38.0 ft., OK, shows scribing.  
New BT - 5" Fir N.2°E., 23.7 ft. scribed "1/4 S28 CS BT".

Douglas Co. Surveyors Office - Randall Smith & Stephen Flause - Mar. 6, 1997 - C.S. 64/71-15

-----  
Found - Badly rusted 3/4" I.D. iron pipe protruding 4" above ground. Source unknown.  
24" now 30" dia. 30' high D.Fir snag with a partially healed previously opened blaze bears S.84°W., 35'. OBT.  
18" now 26" dia. D.Fir, with bark scribing visible "1/4 2880" facing corner and "S BT" facing west, bears S.10°W., 38'.  
5" now 17" dia. D.Fir, with a fully healed sing blaze, bears N.2°E., 23.7'.

(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 300240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 28 and 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set -2 3/8" Dia. Brass cap on a 1 3/8" by 32" long iron pipe is set at referenced position of 3/4" I.P, 3/4" I.P. measured 24" long is set a long north edge of BC/IP protrudes 6" above ground.

New BTs- 11" dia. D.Fir, double blazed and scribed "¼ S29 CS BT", bears N.49½°W., 8.8'.  
6" dia. D.Fir, double blazed and scribed "¼ S28 CS BT", bears S.71½°E., 11.1'.

Corner lies at the intersection of down fence lines running east, west and north on a steep northerly slope.

Fd. ok by R. Rice, 7/2004 - M 145-20

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2872, surveyed April 2017/Oct. 2019- (DCSO records Vol. 59 Page 23856-7)

-----  
The ¼ sec. cor. of secs. 28 & 29, perpetuated by Markham in 1949; subsequently perpetuated by Byron in 1963; further perpetuated by Smith, in 1997, monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground (alongside of which is an iron pipe, 1" dia., firmly set, projecting 4" above the ground), with a brass cap (properly) mkd. from which the remains of an original BT

- A decayed fir snag, 22" dia., bears S.84°W., 35.0 ft., with no marks visible on partially healed blaze.
- and a BT mkd. by Markham
- A fir, 28" dia., bears S.10¼°W., 37.5 ft., with scribe marks ¼ 28 visible on bark.
- and a BT mkd. by Byron
- A fir, 23" dia., bears N.0¼°W., 22.7 ft., with a healed blaze.
- and the BTs mkd. by Smith
- A fir, 8" dia., bears S.75¾°E., 10.6 ft., with a healed double blaze.
- A fir, 15" dia., bears N.49¼°W., 9.2 ft., with a healed blaze.