

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7001)

Set ¼ sec. post, from which
A B.Oak 10" dia., bears S.70°E., 260 lks. dist.
A W.Oak 8" dia., bears N.10°W., 350 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7072)

The old post is gone, but both the bearing trees are standing; I restore this corner by setting an Oak post 3 ft. long, 3" sq., 24" in the ground, marked ¼ S on W. face; also set a basalt rock 14x8x6 ins. along side, from which
A B.Oak 30" dia., bears S.70°E., 260 lks. dist. mkd. ¼ S BT.
A W.Oak 15" dia., bears N.10°W., 370 lks. dist. mkd. ¼ S BT.
Both are the old bearing trees, which as the old marks are dim, I remark.

Survey by John H. Markham, Jr - For: Stomar Lumber Co. - Wit: B.E. Blombgren - Feb. 1952 - C.S. File 41/161-1

Determined by O.B.T.:
A 30" W.Oak bears N.12°W., 244 ft. dist. I remarked ¼S20 BT.
A 40" B.Oak bears S.70°E., 172.0 ft. I found scribe and remarked ¼S S21 BT.
At corner point, Set 1" x 30" axle with 6" flange up, from which
A 10" B.Oak bears N.80°E., 30.0 ft. mkd. ¼ S21 BT.
Fences run N-E and W. Fence corner bears N.57°W., 11½ ft.

Survey by William Ruppert - For: Tom & Larry Michaels - Dec. 1980 - M 79-65

Found - Orig. BT, S.70°E., 171.6 ft. Scar and opened rotten face.
30" B.Oak N.70°E., 31.8 ft.
Markham corner was destroyed by road construction.
Set 1" x 16" Iron pipe with 2½" brass cap mkd. T30S R4W ¼ S20 S21 PLS 866 1980. Set 6" below ground on West edge of road.
Set 5 ft. steel fence post 0.5 ft. West.
New BT - 22" W.Oak N.13°30'W., 27.4 ft. scribed ¼ S20 BT.
Fence corner bears N.56°W., 12.3 ft.

continued next page

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, and Robert Browning, Surveying Technician, under Group #1686, surveyed May 1993 thru April. 1995 - (DCSO records Vol. 52 Page(s) 20107)

From the ¼ sec. cor. of secs. 20 & 21, perpetuated by Markham, in 1953, further perpetuated by Ruppert, in 1980, monumented with an iron post, 1" diam., laying horizontal underground, with brass cap mkd., T30S R4W ¼ S20 S21 PLS 866 1980, the iron pipe has been disturbed, therefore the corner position was determined at record bearing and dist. from a remaining original bearing tree:

An oak, 46" diam., bears S.70°E., 260 lks., with healed double blazes.

and a bearing tree mkd. by Markham

An oak, 29" diam., bears N.69½°E., 48 lks., with healed double blazes.

and the remains of a bearing tree mkd. by Ruppert

An oak snag, 16" diam., bears N.11 3/4°W., 41½ lks., with scribe marks ¼ S20 BT visible on open blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" diam., 27" in the ground, with brass cap mkd.

T30S R4W
1/4
S 20 | S 21
1994

Deposit a white "DEEP-1" magnetic marker at base of and iron pipe alongside of stainless steel post.

The corner is located S.52°E., 0.18 chs. of a fence corner, with woven wire fences extending N. and W.