

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 7002)

Set ¼ sec. post at average distance, from which
A W.Oak 4" dia., bears S.35°W., 62 lks. dist.
A Laurel 7" dia., bears N.5°W., 35 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7076)

Set a Fir post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on N. face, from which
A Fir 12" dia., bears N.51½°W., 31 lks. dist. mkd. ¼ S BT
A B.Oak 6" dia., bears S.47°W., 8 lks. dist. mkd. ¼ S BT.
The old post set for this corner, and all the bearing trees have evidently been destroyed by fire about 25 years ago, as there are no trees growing here older than 25 years at the most.

H.L. Eppstein, Co. Surveyor - Wit: William Rachor; Henry Rachor; N.E. Richardson - Oct. 26, 1928 - Vol. 3 Pg. 288-89; M 4-45 - (and "old" corner book, Pg 200)

Set 1¼" x 3 ft. shaft for corner from old BTs. Marked new BT:
8" Fir S.21°W., 6 lks.
30" Fir N.71°E., 25 lks.

Ben B. Irving, D.C.S. - Wit: N.E. Richardson; R.L. Irving - Feb. 26, 1940 - (No record source found; former renewal records #61, states source from C.S. File 16/55 but search did not show as such.)

Set 1" iron bar with the following BT:
8" Fir bearing S. (?)

G.J. Wenderoth, Deputy Co. Surveyor - Nov. 1945 - (No record source found - record comes from former renewal record #69)

Set 1" Iron bar with the following BT:
8" Fir bears S.21°W., 3.96 ft. dist.
30" Fir bears N.62°45'E., 16.5 ft.

B.B.Irving - For: Frank Brown & Jack Gaulke - July 1946 - C.S. File 38/220

Fd. Iron bar and both BTs. 8" Fir S.21°W., 3.96 and 30" Fir N.62°45'E., 16.5 ft.

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 16

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Douglas Co. Surveyors Office - James W. Byron, Deputy - S.A. Bilow; Milo Godfrey, crew - Feb. 19, 1959 - C.S. File 49/134; RM 1-28

Found - 1 1/4" car axle at corner.
Four stumps that have been cut low that check bearings and distances as recorded. No scribing found.
New BTs -16" R.Fir bears N.30 1/2°E., 64.4 ft. scribed 1/4 S9 CS BT.
46" R.Fir bears N.19°W., 275.7 ft. scribed 1/4 S9 CS BT.

Douglas Co. Surveyors Office - Karen Reed; Frank Silagy; Peter Earle, crew - Aug. 20, 1979 - C.S. File 60/34-13

Found - 1 1/4" axle protruding .75 ft. above ground set by Eppstein in 1928.
No original trees found.
A Fir stump approx. 30" dia., bears N.63°E., 16.5 ft., stump badly rotted. (Rec. N.71°E.)
A 16" Red Fir now 18" bears N.30°E., 64.4 ft. with well healed double blaze.
A 46" R.Fir now 54", bears N.19°W., 278.7 ft. with well healed blaze. (Rec. 275.4 ft.) 276.4 ft. to face.
No new monument set.
New BTs -8" D.Fir scribed "1/4 S16 CS BT" in a double blaze bears S.79°E., 97.3 ft.
10" broad leaf Maple scribed "1/4 S16 CS BT" in a double blaze bears S.22°W., 141.9 ft.
Previous renewals do not state bearings and distances from original trees.

B.Shaner, survey for Logan, April 2000 - M132-28 & CS65/30-8A

Found OK,
New accessory - Set 6 foot aluminum post east, 1.0 foot.