

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by William Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 (DCSO records Vol. 17 Page(s) 7106)

Set a stone 14x12x4", 10" in the ground for cor. to secs. 26, 27, 34 and 35, marked with 2 notches on E. and 1 notch on S. edges, from which

A Fir 34" dia., bears N.57 3/4°E., 69 lks. dist. mkd. T30S R4W S26 BT.

A Fir 36" dia., bears S.52 3/4°E., 34½ lks. dist. mkd. T30S R4W S35 BT.

A Chinquapin 12" dia., bears S.71¼°W., 91½ lks. dist. mkd. T30S R4W S34 BT.

A Maple 16" dia., bears N.44½°W., 75 lks. dist. mkd. T30S R4W S27 BT.

Survey by John H. Markham, Jr. - Wit: R.G. Boyd - For: Stomar Lumber Co. - Feb. 1959 - C.S. File 42/356-7

Determined by OBTs:

40" Fir bears N.58°E., 45.5 ft.

24" Maple snag bears N.44°W., 49.5 ft., found scribe.

At corner point found stone and SET 1/2" x 24" iron rod, from which

18" Yew bears N.48°W., 58.0 ft. mkd. S27 BT.

4" Laurel bears S.5°E., 28.0 ft. mkd. S35 BT.

4" Chinquapin S.46°E., 48.0 ft. mkd. S35 BT.

4" Maple N.67°E., 18.0 ft. mkd. S26 BT.

Douglas Co. Surveyors Office - R.B. Kimberling, Deputy - M.C. Cline, crew - Oct. 17, 1977 - C.S. File 59/40-47

Found - A 1/2" x 15" iron rod bent over and pushed out of position by excavated material from road construction, buried 3½ ft.

A 34" Fir stump now 42", bears N.57 3/4°E., 45.5 ft.

A 16" Maple, now size indeterminate, down and badly rotted, bears approx. N.44½°W., 49.5 ft. (OBT)

A Yew snag, 18" dia., 20 ft. high, bears N.48°W., 58.0 ft. Found scribe marks "S27 BT" in double blaze.

A 4" now 5" Chinquapin, uprooted, root hole bears approx. S.46°E., 48.0 ft. found double blaze and scribing "S35-T"

Set a 1" x 30" I.P. from Fir stump, OBT, and Yew snag BT, with brass cap set flush with ground marked:

(Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas County Surveyor
T 30 S R 4 W
S 27 | S 26
S 34 | S 35
1977

Set 1/2" Iron rod at North edge of brass cap, flush with top. Terraced a 10 ft. dia. area around corner to prevent erosion. New BTs -12" Maple bears N.2½°E., 23.4 ft., double blazed and scribed "T30S R4W S26 CS BT".
A 4" Fir bears N.35°W., 26.9 ft. double blazed and scribed "T30S R4W S27 CS BT"
A 4" Alder bears S.76°W., 24.3 ft. bark scribed "T30S R4W S34 CS BT".
A 22" Maple bears S.11°E., 59.4 ft. double blazed and scribed "S35 T30S R4W CS BT".
Corner is in old unit 80 ft. NE. of Road #30-4-26.0, 100 ft. West of West edge of new unit.

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1907, surveyed July 1999/Aug. 1999. (DCSO rec. Vol. 53 page(s) 20649-50)

Beginning at the cor. of secs. 26, 27, 34, & 35, perpetuated by Markham, in 1959, from original evidence no longer in existence, further perpetuated by Kimberling; monumented with an iron pipe, 1¼" dia. firmly set, projecting 1" above ground (alongside of which is an iron rod, ½" dia., firmly set, projecting 1" above ground), with brass cap (properly) mkd. from which bearing trees mkd. by Kimberling, in 1977
A maple, 17" dia., bears N.2½°E., 23.1 ft., with a healed double blaze.
A maple, 27" dia., bears S.12½°E., 60.2 ft., with a healed double blaze.
A fir, 16" dia., bears N.33½°W., 27.8 ft., with a healed double blaze.
and a new bearing tree
A fir, 7" dia. bears S.42½°W. 9.0 ft. mkd. T30S R4W S34 BT
Each new bearing tree has a 2½" x ¼" magnetic nail (Mag Nail) driven at the base on right side-center, unless otherwise described in the corner description.

Fd BC, 4 BTs & steel post by R. Rice 8/7/2012 - C.S. file 65/77-21