

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 500700

PRIMARY CORNER DESCRIPTION C C for Secs. 2 & 3 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7055)

For closing cor. to secs. 2 and 3, I set a Cedar post 4½ ft. long, 4" sq., 24" in the ground, mkd. C C T30S R4W on S. face, S2 on E. face, S3 on W. face, and 2 notches on E. and 4 notches on W. faces, from which
A Fir 24" dia., bears S.43½°E., 25 lks. dist. mkd. T30S R4W S2 BT.
A Fir 18" dia., bears S.73½°W., 22 lks. dist. mkd. T30S R4W S3 BT.

F.C. Frear, Douglas Co. Surveyor - Wit: A. Wallenburg; R. Morrison - Oct/Nov. 1918 - Field Book 14+45; C.S. File 7/18; Vol. 3 Pgs. 29-30; M 1-3

Renew from old government trees. Set in a 1½" x 36" Iron pipe from which the old govt. trees remarked.

Survey by John H. Markham, Jr. - For: Stomar Lbr. Co. - Wit: Dennis and Geo. Vaughn - Nov. 2, 1951 - C.S. File 40/386-2

Determined by O.B.T., a Fir stump bears S.73°W., 14½ ft. dist. (OBT)
At corner point, Set 1" x 30" I.P., from which
A Cedar 6" dia., bears S.8°W., 66½ ft. mkd. 53 2880 BT.
¼ Corner bears East 165.0 ft.
Fork in road bears S.58°W., 88.0 ft.
Corner lies just West edge of upper road.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, crew - Feb. 17, 1972 - C.S. File 53/26-52

Found - 12" Cedar BT mkd. by Markham, S.8°W., 66.5 ft., shows good scar.
At corner point brass cap mkd. County Surveyors Office 1956 T29S R4W CC S3|S2 T30S R4W (No record)
New BT - 8" W.Oak S.55°E., 64.5 ft. mkd. T30S R4W S2 CC CS BT
This corner lies S.86°W., 168.0 ft. of Sec. cor. S35 and as noted, corner lies on W. edge of upper road.
No trace of orig. BTs or I.P. set by Markham.

FD OK by Ron Quimby, March 1996 - M 123-58
Fd. as per record 10/2023 D. Edwards - M182-80