

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6995)

Set 1/4 sec. post at average distance, from which
A B.Oak 6" dia., bears N.50°W., 38 lks. dist.
A W.Oak 12" dia., bears S.45°W., 36 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7046)

1/4 sec.cor., the post is gone but the W.Oak bearing tree in Sec. 23 is still standing; the B.Oak is gone. I restore this cor. by setting a W.Oak post 3 ft. long, 4" sq., 24" in the ground, mkd. 1/4 S on N. face, from which
A B.Oak 8" dia., bears N.11 3/4°E., 47 lks. dist. mkd. 1/4 S BT.
A W.Oak 18" dia., bears S.45°W., 36 lks. dist. mkd. 1/4 S BT. This is the old bearing tree, which I re-mark, the old marks being dim.

F.C. Frear, Deputy Co. Surveyor - Wit: A. Wallenberg; R.d. Morrison - Oct. 31, 1918 (No record source found, see "old" corner renewal Volume, Page 143)

Renew from old BTs.
Set in a 8" x 8" x 18" Creek boulder and a 4" x 36" Cedar stake, from which
A 10" B.Oak bears N.6 3/4°E., 48 lks.
A 24" W.Oak bears S.55 1/2°W., 36 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Mike Darby; Wm. S. Stoffel crew - June 1963 - C.S. File 53/26-62

Found - Orig. 12" now 24" W.Oak S.45°W., 23.8 ft. We open and find good reverse scribing.
NE. BT in slide area.

(Corner is in old logging road near East edge.)

Set Brass cap at cor. mkd: County Surveyors Office
T 30 S R 4 W

1/4 S 14
S 23
1963

New BTs -Rescribed the 24" W.Oak S.48°22'W., 24.3 ft. "1/4 S23 CS BT".

8" W.Oak bears N.86°E., 23.0 ft. scribed "1/4 S14 CS BT."

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 14 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1070, surveyed June 1981/May 1982 - (DCSO records Vol. 43 Page(s) 16822-23)

The ¼ sec. cor., perpetuated and recorded by Byron in 1963, determined at record bearing and distance from the remaining original bearing tree:

A W.Oak 22" dia., bears S.45°W., 36 lks. dist. with illegible scribe marks visible on partially healed blaze.

and the remains of a bearing tree mkd. by Byron:

A root hole bears N.86°E., 35 lks. dist. with a down Oak alongside, 12" dia., with a healed blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 30 S R 4 W
1/4 $\frac{S\ 14}{S\ 23}$
1981

from which new bearing trees:

A Madrone 13" dia., bears N.34½°E., 84½ lks. dist. mkd. ¼ S14 BT on bark.

A Madrone 6" dia., bears S.85½°E., 40½ lks. dist. mkd. ¼ S23 BT on bark.

Corner is located on S. edge of dirt road, 15 lks. wide, bears N.75°E. and S.75°W.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Wit: J.M. Powell - July 11, 1983 - C.S. File 62/9-22

Found - 1981 BLM monument with brass cap properly mkd., firmly set in a vertical position under 15" of fill along southerly side of dirt road.

The stone and stake from 1918 not found.

The brass cap monument from 1963, not found.

Orig. 12" Oak rescribed during 1963 visit, now 33" dia., has partially healed blaze with some scribing visible, bears S.47°W., 23.8 ft. (Rec. S.45°W.)

1981 BT, 7" now 8" Madrone, bark scribed "¼ S23 BT" bears S.85½°E., 26.7 ft.

Unrecorded 1/2" dia. iron pipe with a 1/2" dia. bolt alongside, bears S.25°E., 9.7 ft.

As this monument is firmly set and appears to be safe below the surface, We place an iron fence post and witness sign along northerly edge of monument.

New BT - 9" Madrone double blaze and scribed "¼ S14 CS BT" bears N.45°W., 76.7 ft.