

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 - (DCSO records Vol. 16 Page(s) 6987-88)

Set post cor. of secs. 25, 26, 35 and 36, from which
A Red Fir 10" dia., bears S.30°W., 40 lks. dist.
A Red Fir 15" dia., bears N.35°E., 10 lks. dist.
A Laurel 6" dia., bears S.15°E., 67 lks. dist.
A Laurel 8" dia., bears N.55°W., 60 lks. dist.

(NOTE: The above corner by Ford must be in doubt due to statement by Thiel in Vol. 17 Pg. 7025 - "There is no post or bearing trees to be found, even not a blaze, although there are plenty of Firs around. This confirms the statement of Mr. Briggs, County Surveyor, who has lived at Canyonville for over 35 years, that Deputy Ford did not run this line; neither the South bdy. as he has never discovered any marks. - - - -" (V. Laugen, March 1996)

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #535, dated Feb. 5, 1889 (DCSO records Vol. 17 Page(s) 7027)

Set a Laurel post, 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 25, 26, 35 and 36, mkd. T30S S25 on NE.; R4W S36 on SE.; S35 on SW.; S26 on the NW. faces and 1 notch on S. and E. edges, from which
A Fir 24" dia., bears N.54°E., 75 lks. mkd T30S R4W S25 BT
A Fir 12" dia., bears S.53°E., 22 lks mkd. T30S R4W S36 BT
A Fir 6" dia., bears S.46°W., 26 lks. mkd. T30S R4W S35 BT
A Fir 16" dia., bears N.64½°W., 37 lks. dist. mkd. T30S R4W S26 BT.

Cor. Fd. and tied in GLO survey by Wm. F. Briggs, U.S. Deputy Surveyor under instructions dated Aug. 7, 1891 - (DCSO records, Vol. 17 Page 7099)

Cor. Fd. and tied in GLO survey by Wm. M. Bushey, Deputy Surveyor, under Contract #620, dated June 17, 1893 - (DCSO records, Vol. 17 Page 7107)

Survey by Robert M. Thompson - Wit: W. Fuller - June 25, 1957 - C.S. File 42/289

Find evidence of 4 old BTs:
Fir to NE. gone, stump hole.
Fir to SE., a rotted stump.
Fir to SW OK, old axe work visible but scribing rotted out
Old blazes to S. and W. intersect here. (Cont. Next Page)

TOWNSHIP 30 RANGE 04 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25, 26, 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

I scribe new bearing trees:
18" Chinquapin, S.42°E., 24.9 ft.
10" Madrone N.55°30'E., 26.2 ft.
Old BT rescribe, 26" D.Fir S.46°W., 17.0 ft.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Mike Darby; Milo E. Godfrey, crew - Aug/Sept 1963 - C.S. 53/26-108

Found - 3/4" Iron pipe at corner.
18" Chinquapin to SE., now stump.
10" Laurel N.60°E., 26.2 ft. not N.55°E.
Old BT, now 28" Fir S.46°W., 17.0 ft., center rotted but tree alive, shows scribing.
New BTs -10" R.Fir bears S.31°E., 51.5 ft. scribed T30S R4W S36 CS BT.
8" R.Fir bears N.27°W., 21.8 ft. scribed S26 CS BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #1070, surveyed June 1981/May 1982 - (DCSO records Vol. 43 Page(s) 16805)

At Sec. cor., perpetuated and recorded by Thompson in 1957, and further perpetuated and recorded by Byron in 1963, monumented with an iron pipe, 1/2" dia., firmly set, projecting 6" above ground, from which a bearing tree mkd. by Thiel:

A Fir 29" dia., bears S.46°W., 26 lks. with healed blaze. and a bearing tree mkd. by Thompson:
A Madrone 12" dia., bears N.58°E., 41 lks., with scribe marks S25 BT visible on partially healed double blaze. and bearing trees mkd. by Byron:
A Fir 15" dia., bears S.31½°E., 79 lks. with healed blaze
A Fir 10" dia., bears N.29¼°W., 33 lks. with healed blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 30 S R 4 W
S 26 | S 25
S 35 | S 36
1981

Reset Iron pipe alongside iron post.

Fd. Ok by Kristian DeGroot - 11/2006 - M146-49
Fd. Ok by R. Rice 11/2010 - M161-47
Fd. Ok by D. Edwards, 9/2011 - M162-72