

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 039020

PRIMARY CORNER DESCRIPTION NW Cor. W Weaver DLC #39

Alias 040050 Description Int SE Cor. Bailey DLC #40  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original DLC survey by Bowman and Burnett under Contract date  
Sept. 24, 1855

-----  
(Notes from DLC #39)

Set a post marked as per instructions, from which  
A Maple 12" dia., bears S.44°E., 243 lks.

-----  
(Notes from DLC #40)

A Post marked as per instructions, from which  
Yellow Pine 12" dia., bears N.15°W., 553 lks.

Ben B. Irving - Wit: N.E. Richardson; R.L. Irving - Dec. 13,  
1934 - No record source found - see "old" cor. Bk. Pg. 183 &  
C.S. File 37/186

-----  
As written in "old" Cor. book

Set 8" x 8" stone, set in the ground.

Standard Geological Survey B.M. elevation 642 ft. set 1903,  
bears North 135.7 ft.

Center line of S.P. R.R. bears North, 107.4 ft., point 19.9  
ft. from R.R. Station 1309+68.1 B.C. spiral No. 1407.

As written on C.S. File 37/186 (added 9/30/2005 DCSO - JC)

US GEOLOGICAL SURVEY BM

642 FT

N - 135.7

INT. COR. DLC 40 ROCK 8"X8"

107.4 <sup>C</sup><sub>L</sub> RR

19.9 E to

BC N° 1407 Sta 1309+68' (light pencil - S40°36'E)

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch  
- Aug. 13, 2013 - C.S. File 67/38-53

-----  
Found - A stone 8x9x15" is set plumbly in a vertical  
position approx. 15" below ground (very old N-S  
running fence wire also found at this depth) No  
marks are found on the stone. 1934

No evidence remains of DLC 39 OBT. Near the position  
of the DLC 40 OBT is evidence of a very old,  
large, tree uproot hole.

A USGS bench mark which is a 3¼" dia., brass cap,  
stamped "642 B 1903" set in the top of a pyramid  
shaped concrete post, protruding approx. 15"  
above ground (see DCSO control monument records  
for complete description); bears N.1°E., 135.4  
ft. (rec. North, 135.7 ft.) 1934 cont. next pg

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 039020

PRIMARY CORNER DESCRIPTION NW Cor. W Weaver DLC #39

Alias 040050 Description Int SE Cor. Bailey DLC #40  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

New - The top center of the fd stone monument is referenced out. The stone is removed from the ground and at the referenced position is placed a 20" dia., brass cap on a 1" I.D. x 32" long iron pipe. Top of BC protrudes 1" above ground. The fd. 1934 stone is placed on the north edge of the BC monument with its top just below the ground surface. Cap mkd:

DOUGLAS COUNTY SURVEYOR

T30S R5W

DLC

40 | DLC

39

2013

A 6" dia., iron rod protruding 4" above ground, described as the SW corner of parcel 2 in a survey filed in DCSO records as M58-14; bears N.32°E., 213.0 ft.

A 40" dia., myrtle, not scribed or blazed (this is the only very large, single trunk Myrtle in the vicinity of the corner); bears S.57°E., 90.7 ft.

A 14" dia., maple scribed "INT SE DLC40CS" "BT" on a double blaze; bears S.13¼°W., 124.1 ft.

Note - Monument is on M/L flat pastureland with scattered myrtle, maple, oak and elder. Monument is ~ 1 ft. east of a broken down N-S running wire fence. Compass decl. 15½°E.