

TOWNSHIP 30 RANGE 05 POINT IDENTIFIER # 040040

PRIMARY CORNER DESCRIPTION SSE Cor. Bailey DLC #40

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original DLC survey by Bowman and Burnett under Contract date Sept. 24, 1855 - (DCSO DLC records Page 620)

Set post marked a quadrangular trench & stone in the center as per instructions.

Raymond Brown - For: Cow Creek Bank of Umpqua Tribe of Indians - May 2012 - M157-54

** to re-define the location of the SE corner of DLC #40, I used the bearing-bearing intersection method ** (Narrative)
Set - 2" iron pipe with brass cap attached, mkd: "PLS 2391 SE COR DLC 40 2101", from which
1" iron pipe, bent and off line, bears N.2°05'20"W., 22.08' (Vol. 8 Pg. 32)
AP, Axle at fence corner, no record - accepted, bears N.0°32'14"W., 222.46'
NE Cor. DLC 41, axle w/gear, bears S.89°44'50"W., 231.36'
1" iron pipe, bears S.89°53'50"W., 271.74' (Vol. 8 Pg. 32)